

**NEW GOLD RAINY RIVER MINE
APPENDIX K
COMPLAINTS REPORTS TO FIRST
NATIONS AND COMMUNITIES**

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period November 26 - December 2, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MECF
207931	SPILL	New Gold	Land	11/26/18 12:00 AM	Hydrocarbon	Land	70 Liters	Fuel escaped from the low flow hose while equipment was parked. The handle had been removed and not properly capped off.	Spill pads were used and contaminated material was removed and placed in a certified containment bin for removal from site.	NO	NO
208024	SPILL	New Gold	Land	11/27/18 12:00 AM	Tailings	Land	30 Liters	The collar that was installed onto the tailings line came loose and sprayed from the side. Most of the spray was contained but some sprayed onto the tailings line roadway.	The spray was located quickly and maintenance tightened the collar. Soil was scooped up and placed in the tailings spill pond.	YES	YES

New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period October 29 - November 4, 2018

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
206151	Spill	Contractor	Land	10/31/18 11:57 AM	Hydrocarbon	Land	3 Liters	While working, dozer operator noticed hydraulic oil leaking from machine.	Equipment was shut down, spill pads were placed. 1/2 cubic meter of material was removed and placed in certified containment bin for removal from site.	No	No

New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period November 19 - 25, 2018

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MECP
207632	Spill	Contractor	Land	11/21/18 12:00 AM	Hydrocarbon	Land	3 Liters	Oil was observed leaking from an idling dozer.	Equipment was shutdown immediately, spill tray was placed under dozer. Contaminated material was scraped up and placed in a certified containment bin for removal from site.	No	No
207671	Spill	New Gold	Air	11/22/18 12:00 AM	Dust	Air		Due to lack of water in cell 1 of the TMA and windy conditions, dust was created and blew outside the mine footprint.	Water was placed in cell 1 to prevent dust from forming.	Yes	Yes
207831	Spill	New Gold	Land	11/25/18 12:00 AM	Hydrocarbon	Land	20 Liters	Leak from Fuel Supply Truck	Dirt and gravel were scraped from the spill area and placed in certified containment bin for removal from site.	No	No

New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period May 14 to 20, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	Contractor	4A Stockpile West side of Georgeson Road	17/05/2018 6:30 AM	Hydrocarbon	Land	10 L	While 350 excavator was operating on top of sand stockpile a hydraulic hose ruptured and sprayed 10 liters of hydraulic oil onto the pile	Excavator shut down. Spill tray and pads in place. Supervisor and Safety notified. Maintenance on scene to repair failed hose. Clean up was successful.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period Jan 1st - 7th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	Mill Operations	2018.01.03 08:30	Reclaim Water	Land	500 L	Conveyor transfer tower fire suppression system activated and extinguished by a false alarm (which was a frozen pipe) spilling 500 L of reclaim water.	Reclaim water that travelled outside of west access door froze. Ice material was scraped up and returned to mill process. Reject sump filled and was pumped back onto mill process.	Yes	Yes

New Gold Rainy River Mine Weekly Spill Report for Period Jan 8th to 14th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	Contractors	2018.01.09 22:00	Diesel	Land	0.75 L	An overflow of fuel tank on service truck resulted in 0.75 L of diesel fuel spilled on ground at Marr site fueling facility.	Approximately 0.75 L of diesel fuel mixed with snow was removed and placed into containment bin for removal from site. Equipment was cleaned and all materials disposed of properly.	No	No
Spill	New Gold	Construction	2018.01.10 15:00	Motor Oil	Land	30 L	Excavator working on breaking materials at Dam 4/5 lost it's environmental plug and spilled 30 L of motor oil on the ground.	Engine alarm was triggered and equipment immediately shut down. Spill pads were placed, scene frozen and mechanic called for repair. Environmental drain plug re-installed, excavator oil replaced. Approximately 2 m2 of materials (rock and spill pads) placed into contamination bin for removal from site.	No	No
Spill	New Gold	Construction	2018.01.12 11:15	Glycol	Land	1.5 L	Preset-Piling Loader operator drove over glycol line which punctured hose causing ~1.5L spill	Contained spill with pads. Glycol line shut off and contractor notified to remove/repair the line. Glycol fluid leaked out of the line onto a poly sheet which contained the spill from expanding out on the ground. Glycol line was under a tarp which was covered and right beside route where equipment travels. Mitigation includes placing delineators along outside edge of glycol lines around work area. Locate edge of tarp and glycol line. Poly sheet, spill pads and snow placed into hazardous material bag for removal from site.	No	No
Spill	New Gold	Construction	2018.01.13 00:00	Motor Oil	Land	2.5 L	Excavator cooler coupler fitting shrunk in cold temperature and caused oil leak.	Scene frozen. Labor crew called in for cleanup. Mechanic called to assess and repair excavator, spill tray placed under area to prevent further contamination. Mechanical assessment was the cooler coupler rubber shrunk due to extreme temperatures (-35 deg C or below). All containments have been successfully removed and disposed of. Approximately 1/8 of contamination bag placed into bin for removal from site.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period Jan 15th to 21st, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	Site Services	2018.01.15 12:30	Hydraulic Oil	Land	12 L	Sand truck was plowing snow at Barron site and blew a hydraulic hose, spilling 12 L of hydraulic oil. Operator shut off truck and used spill kit to contain leak.	Contaminated oil and snow was scraped up and placed into two barrels. Barrels were moved to containment area for removal from site. Mechanic replaced hydraulic hose on truck.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period Jan 22nd to 28th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	Contractors	2018.01.24 0915	Hydrocarbon	Land	10 L	Dozer operator working in Borrow Pit 9E noticed hydraulic oil dripping onto ground.	Equipment shut down and spill tray placed under spill. Dozer was repaired and moved. Spill was successfully cleaned up. Ice, snow and spill pads were collected in 4 five gallon pails and placed in bins for removal from site.	No	No
Spill	New Gold	Contractors	2018.01.27 0253	Hydrocarbon	Land	20 L	Operator loading material into articulated rock truck noticed hydraulic oil leaking from hydraulic hose.	Equipment was shut down immediately by operator and spill pads were placed. Supervisor & Safety dept. notified. 3 m2 of contaminated rock removed and placed into containment bin for removal from site.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period Jan 29th to Feb 4th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	Contractors	2018.02.03 23:13	Hydrocarbon	Land	3 L	The turbo line broke on a haul truck causing a motor oil leak.	Equipment shut down and spill tray placed under spill. Mechanic noticed spill originated from turbo line break and repaired it. Three litres of motor oil spilled on snow pack. It was removed and placed into contaminated waste bin for disposal off site site.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period Feb 19th to 25th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	Mill Operations	21.02.2018 10:20	Pebble Lime	Land	<5 L	Lime truck driver noticed lime coming out of top of fill pipe on lime silo at top elbow. Shut down the transfer process right away, small amount of pebble lime fell down from hole in pipe covering snow around lime silo.	Operations grabbed skid steer and scraped up affected snow and brought inside mill to floor sump to put lime into mill process. Maintenance to patch the transfer pipe until a replacement pipe arrives.	No	No
Spill	Contractor	Construction	21.02.2018 10:05	Antifreeze	Land	5L	Operator was pushing debris off access road to collection ditch when he noticed an antifreeze leak on the right side of the dozer	Dozer was shut down immediately. Spill tray and diapers put in place. Supervisor and Safety notified. Clean up successful. Maintenance on scene to replace split radiator hose.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period Mar 5th to 11th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	Contractor	Construction	05.03.2018 14:30	Hydraulic Fluid	Land	4L	Excavator was walking from North Dam to reclaim well on road by Dam 4. Operator felt controls were slow and stopped the equipment. He discovered oil leaking from the line leading to the final drive.	Excavator was shut down immediately. Spill pads and spill snakes put in place. Supervisor and Safety notified. Maintenance replaced hose line leading to final drive. Clay, rock, soiled spill pads and snakes placed into contaminated soil bin for removal from site. Clean up was successful.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period Mar 12th to 18th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	Contractor	Construction	12.03.2018 14:30	Hydrocarbons	Land	25L	Hydro-carbons noticed floating on top of water during spring thaw event. Hydrocarbons had accumulated on snow from equipment parked in laydown area over the winter months.	Approximately 1 m3 of contaminated material consisting of snow, sand and gravel plus spill pads and noodles was collected and placed into containment bin for removal from site.	No	No
Spill	New Gold	Warehouse	16.03.2018 14:50	Gear Lubricant	Land	136L	During movement of 45 Gallon drums of Vultrex Gearshield, the telehandler punched a hole in a drum causing 3/4 of the contents to leak out onto the snow and ice surface in the laydown yard at Barron warehouse.	Hydrocarbon, snow, ice, sand and spill pads collected and placed into 40 Gallon drums for removal from site by GFL.	Yes	Yes

New Gold Rainy River Mine Weekly Spill Report for Period Mar 26th to April 1st, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	Contractor	Fueling Facility	28.03.2018 10:00	Hydrocarbons	Land	40L	Fuel tanker overfilled clear diesel fuel tank as high level alarm did not sound. Majority of spill was contained with secondary containment catchment area. Approximately 40 L of clear diesel overflowed onto ground surface beside containment area.	Fueling facility closed. Clear diesel tank emptied and moved out of secondary containment area. Hydrocarbon contaminated gravel, sand and soil removed and placed into containers for removal from site by GFL. New secondary containment liner placed. Clean fill added and pad leveled out. Fuel tank positioned back into place.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period April 2nd to 8th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	Contractor	Roen Road	07.04.2018 09:00	Hydrocarbons	Land	1L	Ambulance (EV01) on route to fuel at Marr Site stalled on the road. Another guard arrived on the scene in the morning and noticed motor oil had been leaking from the engine.	Security guard used spill pads and placed a spill tray under the vehicle. The ground was cleaned and contaminated materials placed into pails for removal from site. Ambulance was towed to main plant site for maintenance.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period April 9th to 15th, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	Contractor	TMA Cell 1 south Laydown	13.04.2018 17:31	Hydrocarbons	Land	<50 L	Excavator undergoing repairs leaked unknown quantity of hydrocarbons onto ground surface in equipment laydown yard.	Spill discovered and contained. Excavator to be repaired and moved off site. Spill report with disposal documentation will be provided once cleanup is completed.	No	No

New Gold Rainy River Mine Weekly Spill Report for Period April 16 to 22, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	Open Pit	21.04.2018 030:20	Hydrocarbons	Land	30 L	Fuel truck filling excavator at primary crusher pad had a rupture in the fuel line. Spill tray overflowed with 30 L leaking onto crusher pad.	Spill pads were placed. Main fuel valve shut off. Labourers cleaned up 15 gallons of crushed rock and spill contaminated pads into a 45 gallon barrel. Spill tray cleaned out by Lube truck. Barrel transported to Laydown 7 for pickup by GFL.	No	No
Spill	Contractor	TMA North Dam	21.04.2018 18:15	Chemical	Land	450L	Loader operator punctured propylene glycol tote with forks causing glycol to spill onto frost protection sand.	Equipment and operators assisted in cleanup. Glycol contaminated sand was dug up and placed into contaminated soil bin for removal from site. Area inspected by New Gold Environment.	Yes	Yes

New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period April 22 to 29, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	Contractor	Sediment Pond 1 Construction Area	27.04.2018 15:21	Hydrocarbon	Land	4 L	Komatsu 400 rock truck waiting to be loaded began to leak hydraulic fluid which was noticed by another driver. Driver informed rock truck driver, who immediately stopped the truck and began to control the spill.	Spill trays and spill diapers used to control spill and clean up ground surface. Two 20 Litre pails of contaminated rock and soil were collected. Pails of contaminated materials stored at MCL Laydown area and will be removed from site by certified hazardous waste carrier.	No	No
Exceedence	New Gold	Operations	27.04.2018 10:30	24-hr Total Suspended Particulates and Iron	Air	N/A	Laboratory results for March air quality monitoring at Gallinger Road air quality station indicated exceedance of total suspended particulates (TSP) and iron. Exceedences caused by increased vehicle traffic along Gallinger Road.	Remediation includes immediate closure of Gallinger Road to all mine employees travelling to and from the site and regular patrolling by New Gold Management to enforce closure.	Yes	Yes

New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period April 30 to May 06, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	Contractor	Haul Road 8	06.05.2018 12:25	Hydrocarbon	Land	10 L	Komatsu 400 rock truck driving to waste dump blew right front tire. Operator attempted to move truck to a safe location when hose ruptured leaking hydraulic fluid on the road. Driver placed spill tray, spill pads and absorbent socks on ground underneath truck to control the spill.	Two bags of used spill pads and socks were collected along with three 5-gallon pails of rock and gravel. These materials are stored at MCL Laydown area and will be removed from site by certified hazardous waste carrier.	No	No
Potential Exceedance	New Gold	Operations	05.05.2018 17:30	Monitoring equipment recorded sound levels exceeding a 50 dBA sound threshold	Noise	>50 dBA	Acoustic audit monitoring equipment in Whip-poor-will habitat areas recorded noise levels exceeding permitted limits on two occasions. Monitoring equipment recorded sound levels of 60 dBA at 3 am on May 1st and 52 dBA at 11 pm on May 3rd.	A review of sound recordings found thunderstorm activities and wildlife sounds (birds chirping and frogs croaking) to be sources of noise. As the noise was unrelated to operations or construction activities, permit conditions were not exceeded and mitigation was not required. Consistent with permit conditions, the MNRF was notified about the event.	No	No

New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period May 07 to 13, 2018

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	Mill Processing Plant	13.05.2018 18:10	Chemical	Land	26 kg	Transport driver was transferring high calcium lime from tanker truck to the lime silo on the plant site. During the transfer, the delivery hose ruptured spilling approximately 26 kg of granular lime onto the ground.	Granular lime, gravel and dirt collected by mini Bobcat excavator and shoveled into the mill for disposal. Contractor required to replace hose and maintain inspection records on site.	Yes	Yes

**New Gold Rainy River Mine Weekly Exceedance and Spill Report
for Period May 28 to June 3, 2018**

Spill Report	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill Report	New Gold - Operations	Plant site, haul truck shop	5/28/2018 8:40 AM	Hydrocarbon	Land	20 Liters	Operator was loading up GFL truck with waste oil totes behind the Haul Truck Shop. He had a spotter on both sides assisting him to line up the forks properly under the tote. As he approached the tote the wheels of the loader went over a small hump in the road causing the forks to raise enough to puncture the bottom of the tote. As soon as the spotter saw it happen he had the operator tip the tote on its side to minimize the oil loss he had made sure the lid was tight on the tote a few minutes before they were going to load it so he was confident it was not going to spill out.	Spill was successfully cleaned up	No	No

New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period June 18 - 24, 2018

SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
Spill	New Gold	TMA	6/19/2018 17:30	Hydrocarbon	Land	15 Liters	Loader experienced a puncture to its fuel tank due to a rock rolling down the face of the stockpile.	The operator noticed the puncture quickly and took action with a spill kit and 5 gallon pail. The machine was taken out of service immediately. A site assessment was completed once the spill was contained. Approximately 0.04m ³ of rock were excavated up and contained in certified contamination bin for removal from site.	No	No
Spill	New Gold	Haul Road	6/21/2018 12:45	Chemical	Land	2 Liters	Spill occurred when drill engine overheated causing reservoir to over top.	Spill pads used to clean up area. Contaminated materials collected and disposed of in contaminated materials bin for removal from site.	No	No

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period June 25 to July 1, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
196676	Spill	Contractor	TMA	6/26/2018 20:00	Hydrocarbon	Land	2 Liters	While moving to push gravel, a hydraulic hose ruptured on a 850 Dozer.	Equipment was shutdown immediately. Spill kit was used to contain the spill. Contaminated material (less than 1 cubic meter) of gravel was placed in certified containment bin for removal from site.	No	No

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period July 2 - 8, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
197414	Spill	New Gold	Pit	7/3/2018 4:00	Hydrocarbon	Land	40 Liters	While changing filters on shovel, the valve closing off the fuel line to the filter was not closed all the way and when the filter was removed oil spilled from the line. Leak was the result of a procedural error.	Area was cleaned and material was placed in a certified contamination bin for removal from site. Discussed with Technicians to ensure valves were to closed properly.	No	No
197572	Spill	Contractor	TMA	7/5/2018 9:00	Hydrocarbon	Land	10 Liters	While operating a dozer, operator notice hydraulic oil on the ground. Leak was due to mechanical failure	Dozer was moved to a safe location and shut down. Spill pads were placed on spill. Hydraulic oil and approximately 1 cubic meter of zone 4 sand were removed and taken to certified contamination bin for removal from site.	No	No
197770	Spill	Contractor	Haul Road 8	7/5/2018 18:00	Hydrocarbon	Land	1 Liter	Hydraulic fluid leak was noticed while moving drill. Equipment was shut down.	Spill pads were used to clean the area. Spill pads were placed in certified contamination bin for removal from site.	No	No

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period July 9 - 15, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
197940	Spill	Contractor	Haul Road	7/11/2018 12:30	Hydrocarbon	Land	9 Liters	While driving down haul road, operator noticed oil spray on window.	Machine was moved to a safe location and shut down immediately. Absorbent pads were used to clean up the spill. Approximately 1 cubic meter of clay and 4" rock were taken to certified contamination bin for removal from site.	No	No
198261	Spill	Contractor	TMA	7/14/2018 16:30	Hydrocarbon	Land	1 Liter	Water pump tipped over causing motor oil leak.	Spill was contained and cleaned. Contaminated material removed from location and taken to certified contamination bin for removal from site.	No	No
198301	Spill	Contractor	Borrow Pit	7/15/2018 17:00	Hydrocarbon	Land	115 Liters	Excavator blew hydraulic line while loading clay into rock truck in Borrow Pit.	Spill kit was used and area was scraped clean and 40 tons of clay material was placed in certified contamination bin for removal from site.	Yes	Yes

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period July 16 - 22, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
198306	Spill	Contractor	TMA	7/16/2018 18:45	Hydrocarbon	Land	2.5 Liters	Approximately 2.5 liters of hydraulic oil sprayed to the ground due to o-ring failure.	O-ring immediately replaced. Crew cleaned up approximately 1 cubic meter of gravel, and spill pads taking them to certified containment bin for removal from site.	No	No
198362	Spill	Contractor	Outcrop 3	7/18/2018 10:30	Hydrocarbon	Land	.5 Liter	Approximately .5 liter of hydraulic oil spilled from loose cap on excavator.	Cap was replaced. Workers absorbed spill with pads. A 5 gallon pail of material was removed to certified containnet bin for removal from site.	No	No

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period July 23 - 29, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
198710	Spill	Contractor	TMA	7/23/2018 16:50	Hydrocarbon	Land	3 Liters	Operator noticed a hose failure on adjacent rock truck resulting in 3 liter spill of hydraulic oil.	Equipment was shut down, spill tray and spill pads deployed. Maintenance called to attend. Clean up crew dispatched. Final clean up has been completed and repairs to truck finished. Approximately 50 Liters of zone 5 gravel was removed and placed in certified contaminated bin for removal from site.	No	No
199177	Spill	Contractor	TMA	7/29/2018 10:00	Hydrocarbon	Land	3 Liters	Operator noticed a leak on an excavator.	Equipment was shut down. Rock was cleaned. Approximately 1/4 cubic meter of blast rock and clay was placed in certified containment bin for removal from site. Equipment was repaired and put back into service.	No	No

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period July 30 - August 5, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
199826	Spill	Contractor	TMA	8/3/2018 10:55	Hydrocarbon	Land	16 Liters	Hydraulic oil spill caused by hose connection failure after being changed out on excavator.	Excavator was shut off immediately. Spill trays and kits were used. Approximately 1 cubic meter of blast rock was placed in certified containment for removal from site.	No	No

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period August 13 - 19, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
200337	Spill	Contractor	TMA	8/13/2018 2:50	Hydrocarbon	Land	4 Litres	Approximately 2 to 4 liters of Hydraulic oil spilled when hose became snagged causing the fitting to detach.	Excavator was shut down, spill pads/socks & absorbent granule materials spread out. Clean up crew called to attend scene. Mechanic removed damaged hose to conduct repair to fitting. 3 cubic feet of clay was removed. Contaminated materials placed into bags and placed in certified disposal bin for removal from site.	No	No

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period August 20 - 26, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
200812	Spill	New Gold	Process Plant	8/20/2018 4:00	Process Water	Land	57 Liters	During pumping of water from inside the process mill pump discard line flipped back over secondary containment wall spilling 57 L of process water onto the access road of door 17W.	Water and mud scrapped up from in front of 17W door and deposited into leach tank secondary containment area. Spill successfully cleaned up by 18:00 hours.	Yes	Yes
201227	Spill	Contractor	WMRS	8/25/2018 8:20	Chemical	Land	10 Liters	Radiator hose clamp loosened on a rock truck and approximately 10 liters of engine coolant spilled.	Equipment was shut down and spill pads placed. Maintenance dispatched to affect repairs. Grader was used to smooth road surface. Approximately 0.5 m3 of loose gravel and clay was placed in certified containment bin for removal from site.	No	No

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period August 27 - September 2, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
201916	Spill	New Gold	Process Plant	8/31/2018 10:30	Process Water	Land	20 Liters	Water from the grinding circuit migrated out the door 11E.	Water and mud scraped up and deposited into leach tank secondary containment area. Spill successfully cleaned.	YES	YES

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period September 10 - 16, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
202571	Spill	New Gold	Process Plant	9/13/2018 0:15	Tailings Slurry	Land	1000 Liters	A tailings pump kicked out and slurry overflowed the containment and flowed outside doors 9E and 4N.	Grinding operator had a loader operator dump sand at the effected doors to limit the spill out the doors. The spill was cleaned up during the night shift.	YES	YES

Twila Griffith

From: Twila Griffith
Sent: Wednesday, March 7, 2018 11:58 AM
To: Daryl Ellis; Hubert Schimann; Stacey Jack; Sylvie St.Jean
Cc: Alyson Bisson; Carolyn Winik; Darrol VanDeventer; Don Emms; Leo Faykes; Mitch Lepage; Russ McMahon; Tammy Grinsell; Thomas Waters; Tim Friesen; Will McGinnis
Subject: New Gold Rainy River Mine Spill Report for period Feb. 26 - Mar. 04, 2018

Hello,

There were no reported spills during the period of February 26 to March 04, 2018.

Kindest regards,

Twila Griffith M.Sc.
Senior Environmental Specialist

New Gold Inc.
Rainy River Mine
5967 Highway 11/71, P.O. Box 5, Emo
Ontario, Canada, POW IEO
P: +1 (807) 482-0900 ext 8064
M: +1 (807) 708-2407
twila.griffith@newgold.com

www.newgold.com
TSX/NYSE MKT:NGD

**New Gold Rainy River Mine Weekly Exceedance
and Spill Report for Period June 25 to July 1, 2018**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MOECC
196676	Spill	Contractor	TMA	6/26/2018 20:00	Hydrocarbon	Land	2 Liters	While moving to push gravel, a hydraulic hose ruptured on a 850 Dozer.	Equipment was shutdown immediately. Spill kit was used to contain the spill. Contaminated material (less than 1 cubic meter) of gravel was placed in certified containment bin for removal from site.	No	No