

**NEW GOLD RAINY RIVER MINE
APPENDIX J
DUST MANAGEMENT RESULTS**

newgold™ Rainy River Project

Water Application and Truck Maintenance Form

Truck ID: 7-563	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
---------------------------	-------------------------------	------------------------------------

Drivers Name: Scott Phipps	Date: June 2020-05-09
-----------------------------------	------------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 9	Dam 5 Water Tree	113	South Dam Haul Road
May 9	Dam 5 Water Tree	113	Sig Crusher

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
New Gold RRP Environment Department
On-call Phone: 807-632-6152

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
---------------------------	----------------------------------	------------------------------------

Drivers Name: Scott P	Date: June MAY 10
------------------------------	-------------------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 10	Dam 5	111 3	SOUTH DAM HAUL ROADS
May 10	Dam 5	1 1	SIS CRUSHER

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
New Gold RRP Environment Department

On-call Phone: 807-532-6152

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Scott Pippus	Date: May 11/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 11	Dam 5	6	South Dam Haul Road
May 11	Dam 5	3	SNL crusher

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 16/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 16	Dam 5 Water tree	4	South Dam
May 16	Dam 5 Water tree	5.5	Haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 17/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 17	Dam 5 Water tree	3	South Dam
May 17	Dam 5 Water tree	2	Haul roads
May 17	Dam 5 Water tree	4	Ring road
May 17	Dam 5 Water tree	2	Haul to lay down

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Ross Cooper	Date: May 17/2020
----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 17	Dam 5 Water tree	1	South Dam

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 18/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 18	Dam 5 Water tree	4	South Dam
May 18	Dam 5 Water tree	1	Haul roads
May 18	Dam 5 Water tree	5	Ring road
May 18	Dam 5 Water tree	2	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper	Date: May 18/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 18	Dam 5 Water tree	3	South Dam/Haul roads
May 18	Dam 5 Water tree	2	North Dam/haul roads near laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503/4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 19/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 19	Dam 5 Water tree	2 (using 4-504) 2 (using 4-252)	South Dam
May 19	Dam 5 Water tree	1 (using 4-504) 1 (using 4-252)	Haul roads
May 19	Dam 5 Water tree	2 (using 4-504)	SNL crusher
May 19	Dam 5 Water tree	1 (using 4-504)	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

On-call Phone: 807-632-6152

Truck ID: 4-504	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper/Brett Brown	Date: May 19/2020
---------------------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 19	Dam 5 Water tree	2	South Dam core
May 19	Dam 5 Water tree	1	South Dam core and haul road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503/4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 20/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 20	Dam 5 Water tree	1 (using 4-504) 3 (using 4-503)	South Dam
May 20	Dam 5 Water tree	3 (using 4-503)	Haul roads
May 20	Dam 5 Water tree	1 (using 4-503)	SNL crusher
May 20	Dam 5 Water tree	2 (using 4-503)	SNL mechanic tent to laydown 3
May 20	Dam 5 Water tree	3 (using 4-503)	Ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

On-call Phone: 807-632-6152

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Mike Klippenstein	Date: May 20/2020
---------------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 20	Dam 5 Water tree	3	South Dam core
May 20	Dam 5 Water tree	2	haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 21/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 21	Dam 5 Water tree	5	South Dam
May 21	Dam 5 Water tree	3	Haul roads
May 21	Dam 5 Water tree	1	SNL crusher
May 21	Dam 5 Water tree	2	SNL mechanic tent to laydown 3
May 21	Dam 5 Water tree	4	Ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Brett Brown	Date: May 21/2020
----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 21	Dam 5 Water tree	2.5	South Dam core/haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503/4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 22/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 22	Dam 5 Water tree	2 (using 4-503) 1 (using 4-252)	South Dam
May 22	Dam 5 Water tree	1 (using 4-503) 1 (using 4-252)	Haul roads
May 22	Dam 5 Water tree	1 (using 4-252)	SNL crusher
May 22	Dam 5 Water tree	1 (using 4-252) 1 (using 4-503)	SNL mechanic tent to laydown 3
May 22	Dam 5 Water tree	2 (using 4-252) 2 (using 4-503)	Ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 23/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 23	Dam 5 Water tree	2	South Dam
May 23	Dam 5 Water tree	1	Haul roads
May 23	Dam 5 Water tree	0.5	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Brett Brown	Date: May 23/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 23	Dam 5 Water tree	1	South Dam core/haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 24/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 24	Dam 5 Water tree	2	South Dam
May 24	Dam 5 Water tree	1	Haul roads
May 24	Dam 5 Water tree	2	SNL mechanic tent to laydown 3 and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 4-252/4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 25/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 25	Dam 5 Water tree	4 (using 4-252)	South Dam
May 25	Dam 5 Water tree	1 (using 4-251)	SNL mechanic tent to laydown 3
May 25	Dam 5 Water tree	2 (using 4-252) 1 (using 4-251)	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Scott Pippus	Date: May 27/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 27	Dam 3	4	South Dam
May 27	Dam 3	1	SNL mechanic tent to laydown 3
May 27	Dam 3	2	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Scott Pippus	Date: May 28/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 28	Dam 3	3	South Dam
May 28	Dam 3	1	SNL mechanic tent to laydown 3
May 28	Dam 3	1	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Trevor Bailey	Date: May 29/2020
-----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 29	Dam 3	3	South Dam clay core

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Chris Sanford	Date: May 30 to June 3/2020
------------------------------------	------------------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 30 th	Dam 5 Water tree	4	South Dam clay core
May 31 st	Dam 5 Water tree	3	South Dam clay core
June 1 st	Dam 5 Water tree	2	South Dam clay core
June 2 nd	Dam 5 Water tree	4	South Dam clay core
June 3 rd	Dam 5 Water tree	3	South Dam clay core

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: June 4/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
June 4	Dam 5 Water tree	2	South Dam clay core
June 4	Dam 5 Water tree	2	Haul roads
June 4	Dam 5 Water tree	1	Crusher/ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: June 5/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
June 5	Dam 5 Water tree	3	South Dam clay core
June 5	Dam 5 Water tree	6	Haul roads/Ring roads
June 5	Dam 5 Water tree	1	Crusher
June 5	Dam 5 Water tree	2	Mech tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper	Date: June 5/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
June 5	Dam 5 Water tree	1	South Dam clay core
June 5	Dam 5 Water tree	2	Haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: June 6/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
June 6	Dam 5 Water tree	2	South Dam clay core
June 6	Dam 5 Water tree	4	Haul roads/Ring roads
June 6	Dam 5 Water tree	1	Crusher
June 6	Dam 5 Water tree	1	Mech tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper	Date: June 6/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
June 6	Dam 5 Water tree	1	South Dam clay core
June 6	Dam 5 Water tree	4	Haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: June 11/2020
-----------------------------------	---------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
June 11	Dam 5 Water tree	0	South Dam clay core
June 11	Dam 5 Water tree	3	Haul roads/Ring roads
June 11	Dam 5 Water tree	1	Crusher
June 11	Dam 5 Water tree	1	Mech tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/12		Dam 5 Water tree		Haul Road 13	4
2020/06/12		Dam 5 Water tree	South Dam	Haul road on the east side of the dam	3
2020/06/12		Dam 5 water tree	South Dam Clay core		2
2020/06/12		Dam 5 Water tree	Crusher		1
2020/06/12		Dam 5 Water tree		Mechanic tent to laydown 3 (Dam 3 roads)	1

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/13	8:00am	Dam 5 Water tree		Haul Road 13	1
2020/06/13	8:45am	Dam 5 Water tree		South Dam haul road	1
2020/06/13	9:30am	Dam 5 water tree	South Dam Clay core		1
2020/06/13	10:40am	Dam 5 Water tree		South Dam haul road	1
2020/06/13	11:20am	Dam 5 Water tree		Dam 3 roads	1
2020/06/13	12:45pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/13	1:50pm	Dam 5 Water tree		Haul Road 13	1
2020/06/13	2:45pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/13	5:30pm	Dam 5 Water tree		Haul Road 13	1
2020/06/13	6:50pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/13	8:05pm	Dam 5 Water tree		Haul Road 13	1
2020/06/13	8:50pm	Dam 5 Water tree		Haul road 8	1
2020/06/13	9:55pm	Dam 5 Water tree		Haul road 13	1
2020/06/13	10:43pm	Dam 5 Water tree		Dam 3 roads	1
2020/06/13	12:40am	Dam 5 Water tree	South Dam Clay core		1
2020/06/13	1:40am	Dam 5 Water tree		South Dam haul road	1
2020/06/13	2:50am	Dam 5 Water tree		Haul Road 13	1
2020/06/13	4:00am	Dam 5 Water tree	South Dam Clay core		1
2020/06/13	4:45am	Dam 5 Water tree		Haul Road 13	1
2020/06/13	5:40am	Dam 5 Water tree		South Dam haul road	1
2020/06/13	6:20am	Dam 5 Water tree		Haul Road 13	1
TOTAL LOADS					21

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/14	8:35am	Dam 5 Water tree		South Dam haul road	1
2020/06/14	9:05am	Dam 5 Water tree	South Dam Clay core		1
2020/06/14	10:10am	Dam 5 water tree		Mech tent to LD 3	1
2020/06/14	12:25pm	Dam 5 Water tree		Dam 3 haul road	1
2020/06/14	1:35pm	Dam 5 Water tree		South Dam haul road	1
2020/06/14	2:30pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/14	3:00pm	Dam 5 Water tree		South Dam haul road	1
2020/06/14	4:25pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/14	5:00pm	Dam 5 Water tree		South Dam haul road	1
2020/06/14	5:35pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/14	6:00pm	Dam 5 Water tree		South Dam haul road	1
2020/06/14	6:50pm	Dam 5 Water tree	South Dam Clay core		1
TOTAL LOADS					12

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/14	8:10am	Dam 5 Water tree	South Dam Clay core		1
2020/06/14	9:22am	Dam 5 Water tree		South Dam haul road	1
2020/06/14	10:22am	Dam 5 water tree		Haul Road 13	1
2020/06/14	11:50am	Dam 5 Water tree		Dam 3 roads	1
2020/06/14	1:25pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/14	3:00pm	Dam 5 Water tree		South Dam haul road	1
2020/06/14	3:51pm	Dam 5 Water tree		Haul Road 13	1
2020/06/14	5:00pm	Dam 5 Water tree		South Dam haul road	1
2020/06/14	6:05pm	Dam 5 Water tree		Haul Road 13	1
2020/06/14	6:51pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/14	8:15pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/14	9:00pm	Dam 5 Water tree		Haul road 13	1
2020/06/14	9:50pm	Dam 5 Water tree		South Dam haul road	1
2020/06/14	10:45pm	Dam 5 Water tree		Haul road 8	1
2020/06/15	12:10am	Dam 5 Water tree		Haul road 13	1
2020/06/15	1:00am	Dam 5 Water tree		Dam 3 roads	1
2020/06/15	2:30am	Dam 5 Water tree		Haul Road 13	1
2020/06/15	4:10am	Dam 5 Water tree		South Dam haul road	1
2020/06/15	5:00am	Dam 5 Water tree		Haul Road 8	1
2020/06/15	5:45am	Dam 5 Water tree		South Dam haul road	1
2020/06/15	6:45am	Dam 5 Water tree		Haul Road 13	1
TOTAL LOADS					21

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/15	1:00pm	Dam 5 Water tree		South Dam haul road	1
2020/06/15	1:30pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/15	3:45pm	Dam 5 water tree		South Dam haul road	1
2020/06/15	4:30pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/15	6:00pm	Dam 5 Water tree		South Dam haul road	1
2020/06/15	8:40pm	Dam 5 Water tree		Haul road 13	1
2020/06/15	9:20pm	Dam 5 Water tree		South Dam haul road	1
2020/06/15	10:05pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/15	11:20pm	Dam 5 Water tree		Haul road 8	1
2020/06/15	12:30am	Dam 5 Water tree		Haul road 13	1
2020/06/15	1:30am	Dam 5 Water tree		Mech tent to laydown 3	1
2020/06/15	2:20am	Dam 5 Water tree	South Dam Clay core		1
2020/06/15	3:55am	Dam 5 Water tree		Haul road 13	1
2020/06/15	4:49am	Dam 5 Water tree		South Dam haul road	1
2020/06/15	5:55am	Dam 5 Water tree		Haul road 8	1
2020/06/15	6:30am	Dam 5 Water tree		Haul road 13	1
			TOTAL LOADS		16

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/15	8:15am	Dam 5 Water tree	South Dam Clay core		1
2020/06/15	9:24am	Dam 5 Water tree		South Dam haul road	1
2020/06/15	10:08am	Dam 5 water tree		Haul road 13	1
2020/06/15	11:10am	Dam 5 Water tree		South Dam haul road	1
			TOTAL LOADS		4

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/15	12:30pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/15	1:30pm	Dam 5 Water tree		Haul road 13	1
2020/06/15	2:00pm	Dam 5 water tree		South Dam haul road	1
2020/06/15	2:40pm	Dam 5 Water tree		Mech tent to Laydown 3	1
2020/06/15	3:50pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/15	4:30pm	Dam 5 Water tree		Haul road 13	1
2020/06/15	5:30pm	Dam 5 Water tree		South Dam haul road	1
2020/06/15	6:05pm	Dam 5 Water tree		Haul road 13	1
2020/06/15	6:44pm	Dam 5 Water tree		South Dam haul road	1
			TOTAL LOADS		9

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/23	8:00am	Dam 5 Water tree	South Dam Clay core		1
2020/06/23	8:50am	Dam 5 Water tree		Ring Road	1
2020/06/23	9:30am	Dam 5 Water tree		Haul Road 13	1
2020/06/23	10:00am	Dam 5 Water tree	South Dam Clay core		1
2020/06/23	10:35am	Dam 5 Water tree		Ring Road	1
2020/06/23	11:25am	Dam 5 Water tree		Haul Road 13	1
2020/06/23	12:05pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/23	12:50pm	Dam 5 Water tree		Ring Road	1
2020/06/23	2:30pm	Dam 5 Water tree		Haul Road 13	1
2020/06/23	3:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/06/23	4:25pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/23	5:10pm	Dam 5 Water tree		Haul Road 13	1
2020/06/23	5:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/06/23	7:55pm	Dam 5 Water tree		Ring Road	1
2020/06/23	8:25pm	Dam 5 Water tree		South Dam Haul Road	1
2020/06/23	2:30am	Dam 5 Water tree		North Dam Haul Road	1
2020/06/23	3:30am	Dam 5 Water tree		Haul Road 8	1
2020/06/23	4:20am	Dam 5 Water tree		South Dam Haul Road	1
			TOTAL LOADS		18

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/24	8:00am	Dam 5 Water tree	South Dam Clay core		1
2020/06/24	9:10am	Dam 5 Water tree	South Dam Clay core		1
2020/06/24	9:45am	Dam 5 Water tree		Ring Road	1
2020/06/24	11:00am	Dam 5 Water tree	South Dam Clay core		1
2020/06/24	12:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/06/24	2:30pm	Dam 5 Water tree		Ring Road	1
2020/06/24	3:10pm	Dam 5 Water tree	South Dam Clay core		1
2020/06/24	4:10pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/06/24	4:50pm	Dam 5 Water tree		Haul Road 13	1
2020/06/24	5:20pm	Dam 5 Water tree		Ring Road	1
2020/06/24	6:30pm	Dam 5 Water tree	South Dam Clay core		1
			TOTAL LOADS		11

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/20	8:05am	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/20	8:30am	Dam 5 Water tree		Ring Road	1
2020/08/20	9:15am	Dam 5 Water tree	South Dam	Haul Road	1
2020/08/20	9:40am	Dam 5 Water tree		Ring Road	1
2020/08/20	10:10am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/20	10:45am	Dam 5 Water tree		Ring Road	1
2020/08/20	11:45am	Dam 5 Water tree		Ring Road	1
2020/08/20	12:25pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/20	12:55pm	Dam 5 Water tree		Ring Road	1
TOTAL LOADS					9

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/27	3:00pm	Dam 5 Water tree	North Dam Spillway		1
2020/08/27	4:00pm	Dam 5 Water tree	North Dam Spillway		1
2020/08/27	6:15pm	Dam 5 Water tree		Ring Road	1
2020/08/27	8:45pm	Dam 5 Water tree	North Dam		1
2020/08/27	9:20pm	Dam 5 Water tree	North Dam		1
2020/08/27	10:05pm	Dam 5 Water tree	North Dam		1
2020/08/27	10:40pm	Dam 5 Water tree	North Dam		1
2020/08/27	12:05am	Dam 5 Water tree	North Dam		1
2020/08/27	1:15am	Dam 5 Water tree	North Dam		1
TOTAL LOADS					9

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/27	8:05pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/27	9:40pm	Dam 5 Water tree		Ring Road	1
2020/08/27	9:10pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/27	9:55pm	Dam 5 Water tree		Laydown 3 to mech tent	1
			TOTAL LOADS		4

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/28	8:00am	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/28	11:45am	Dam 5 Water tree		Ring Road	1
2020/08/28	5:30pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/28	6:15pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		4

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/30	8:15am	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/30	9:15am	Dam 5 Water tree	South Dam	Haul Road	1
2020/08/30	9:45am	Dam 5 Water tree		Ring Road	1
2020/08/30	10:15am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/30	12:15pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/30	12:55pm	Dam 5 Water tree	South Dam	Haul Road	1
2020/08/30	1:40pm	Dam 5 Water tree		Ring Road	1
2020/08/30	2:30pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/30	3:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/30	4:35pm	Dam 5 Water tree		Ring Road	1
2020/08/30	5:05pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/30	545pm	Dam 5 Water tree		Ring Road	1
2020/08/30	6:25pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		13

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

[illegible]

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/02	12:20pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/09/02	1:05pm	Dam 5 Water tree		Ring Road	1
2020/09/02	1:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/02	2:10pm	Dam 5 Water tree		Ring Road	1
2020/09/02	3:05pm	Dam 5 Water tree		Ring Road	1
2020/09/02	4:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/02	5:05pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		7

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/03	4:10pm	Dam 5 Water tree	South Dam	Haul Road	1
			TOTAL LOADS		1

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/04	8:10am	Dam 5 Water tree		Ring Road	1
2020/09/04	8:40am	Dam 5 Water tree		Ring Road	1
2020/09/04	9:10am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/04	9:50am	Dam 5 Water tree		Ring Road	1
2020/09/04	1:30pm	Dam 5 Water tree		Ring Road	1
2020/09/04	2:00pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/04	2:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/04	3:40pm	Dam 5 Water tree		Ring Road	1
2020/09/04	4:20pm	Dam 5 Water tree		Ring Road	1
2020/09/04	4:55pm	Dam 5 Water tree		Ring Road	1
2020/09/04	5:30pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/04	6:15pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		12

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/05	8:30am	Dam 5 Water tree	South Dam	Haul Road	1
2020/09/05	9:20am	Dam 5 Water tree	West Dam 5		1
2020/09/05	9:50am	Dam 5 Water tree		Ring Road	1
2020/09/05	10:35am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/05	11:15am	Dam 5 Water tree		Ring Road	1
2020/09/05	12:00pm	Dam 5 Water tree		Ring Road	1
2020/09/05	1:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/05	1:55pm	Dam 5 Water tree		Ring Road	1
2020/09/05	2:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/05	4:05pm	Dam 5 Water tree		Ring Road	1
2020/09/05	4:55pm	Dam 5 Water tree	South Dam	Haul Road	1
2020/09/05	6:00pm	Dam 5 Water tree		Ring Road	1
2020/09/05	6:35pm	Dam 5 Water tree		Ring Road	1
TOTAL LOADS					13

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/06	8:10am	Dam 5 Water tree	South Dam		1
2020/09/06	8:55am	Dam 5 Water tree		Ring Road	1
2020/09/06	9:30am	Dam 5 Water tree		Ring Road	1
2020/09/06	10:15am	Dam 5 Water tree	South Dam		1
2020/09/06	11:10am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/06	12:15pm	Dam 5 Water tree		Ring Road	1
2020/09/06	12:50pm	Dam 5 Water tree		Ring Road	1
2020/09/06	1:55pm	Dam 5 Water tree	West Dam		1
2020/09/06	2:45pm	Dam 5 Water tree		Ring Road	1
2020/09/06	3:45pm	Dam 5 Water tree		Ring Road	1
2020/09/06	4:55pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/06	5:45pm	Dam 5 Water tree		Ring Road	1
2020/09/06	6:20pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		13

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/07	8:10am	Dam 5 Water tree	South Dam	Haul Road	1
2020/09/07	8:55am	Dam 5 Water tree		Ring Road	1
2020/09/07	9:30am	Dam 5 Water tree		Ring Road	1
2020/09/07	10:10am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/07	10:45am	Dam 5 Water tree	South Dam	Haul Road	1
2020/09/07	12:25pm	Dam 5 Water tree		Ring Road	1
2020/09/07	1:20pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/07	2:00pm	Dam 5 Water tree	South Dam	Haul Road	1
2020/09/07	2:55pm	Dam 5 Water tree		Ring Road	1
2020/09/07	4:35pm	Dam 5 Water tree		Ring Road	1
2020/09/07	5:15pm	Dam 5 Water tree		Ring Road	1
2020/09/07	5:55pm	Dam 5 Water tree		Ring Road	1
2020/09/07	6:40pm	Dam 5 Water tree		Ring Road	1
TOTAL LOADS					13

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/08	8:00am	Dam 5 Water tree	South Dam		1
2020/09/08	8:55am	Dam 5 Water tree		Ring Road	1
2020/09/08	10:10am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/08	11:40am	Dam 5 Water tree	South Dam		1
2020/09/08	12:30pm	Dam 5 Water tree		Ring Road	1
2020/09/08	1:05pm	Dam 5 Water tree	South Dam		1
2020/09/08	2:00pm	Dam 5 Water tree		Ring Road	1
2020/09/08	2:40pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		8

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

[illegible]

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/10	11:55am	Dam 5 Water tree	North Dam		1
2020/09/09	1:00pm	Dam 5 Water tree		Ring Road	1
2020/09/09	1:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/09	2:20pm	Dam 5 Water tree		Ring Road	1
2020/09/09	3:15pm	Dam 5 Water tree	South Dam		1
2020/09/10	4:20pm	Dam 5 Water tree		Ring Road	1
2020/09/10	5:15pm	Dam 5 Water tree	South Dam		1
2020/09/10	5:55pm	Dam 5 Water tree		Ring Road	1
2020/09/10	6:40pm	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		9

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/11	8:00am	Dam 5 Water tree		Ring Road	1
2020/09/11	8:35am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/11	9:15am	Dam 5 Water tree	South Dam		1
2020/09/11	10:00am	Dam 5 Water tree		Ring Road	1
2020/09/11	10:40am	Dam 5 Water tree	West Dam 5		1
2020/09/11	12:00pm	Dam 5 Water tree		Ring Road	1
2020/09/11	12:45pm	Dam 5 Water tree		Ring Road	1
2020/09/11	1:25pm	Dam 5 Water tree	South Dam		1
2020/09/11	2:15pm	Dam 5 Water tree		Ring Road	1
2020/09/11	4:10pm	Dam 5 Water tree	West Dam 5		1
2020/09/11	4:50pm	Dam 5 Water tree	South Dam		1
2020/09/11	5:30pm	Dam 5 Water tree		Ring Road	1
2020/09/11	6:10pm	Dam 5 Water tree		Ring Road	1
TOTAL LOADS					13

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

[illegible]

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

[illegible]

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/14	12:00pm	Dam 5 Water tree	South Dam		1
2020/09/14	3:50pm	Dam 5 Water tree		Ring Road	1
2020/09/14	4:45pm	Dam 5 Water tree	South Dam		1
2020/09/14	5:20pm	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		4

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/15	8:00am	Dam 5 Water tree	South Dam		1
2020/09/15	8:45am	Dam 5 Water tree	South Dam		1
2020/09/15	2:05pm	Dam 5 Water tree		Ring Road	1
2020/09/15	3:10pm	Dam 5 Water tree		Ring Road	1
2020/09/15	4:05pm	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		5

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/16	8:05am	Dam 5 Water tree	South Dam		1
2020/09/16	8:40am	Dam 5 Water tree		Ring Road	1
2020/09/16	9:35am	Dam 5 Water tree			1
2020/09/16	10:15am	Dam 5 Water tree		Ring Road	1
2020/09/16	10:55am	Dam 5 Water tree	South Dam		1
2020/09/16	12:05pm	Dam 5 Water tree		Ring Road	1
2020/09/16	12:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/16	1:35pm	Dam 5 Water tree		Ring Road	1
2020/09/16	2:25pm	Dam 5 Water tree		Ring Road	1
2020/09/16	4:00pm	Dam 5 Water tree		Ring Road	1
2020/09/16	4:35pm	Dam 5 Water tree		Ring Road	1
TOTAL LOADS					11

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/24	3:05pm	Dam 5 Water tree	South Dam		1
2020/09/24	4:05pm	Dam 5 Water tree	South Dam		1
2020/09/24	4:55pm	Dam 5 Water tree		Ring Road	1
2020/09/24	5:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/24	6:10pm	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		5

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/25	5:00pm	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		1

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/26	8:00am	Dam 5 Water tree	South Dam		1
2020/09/26	8:40am	Dam 5 Water tree		Ring Road	1
2020/09/26	11:10am	Dam 5 Water tree	South Dam		1
2020/09/26	11:55am	Dam 5 Water tree	South Dam		1
2020/09/26	12:45pm	Dam 5 Water tree	South Dam		1
2020/09/26	1:30pm	Dam 5 Water tree	South Dam		1
2020/09/26	2:30pm	Dam 5 Water tree	South Dam		1
2020/09/26	3:25pm	Dam 5 Water tree	South Dam		1
2020/09/26	4:05pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/09/26	4:55pm	Dam 5 Water tree	South Dam		1
2020/09/26	5:45pm	Dam 5 Water tree	South Dam		1
2020/09/26	6:25pm	Dam 5 Water tree	South Dam		1
TOTAL LOADS					1

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/27	8:05am	Dam 5 Water tree	South Dam		1
2020/09/27	9:05am	Dam 5 Water tree	South Dam		1
2020/09/27	9:55am	Dam 5 Water tree	South Dam		1
2020/09/27	10:55am	Dam 5 Water tree	South Dam		1
2020/09/27	4:40pm	Dam 5 Water tree	South Dam		1
2020/09/27	5:35pm	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		6

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/28	10:00am	Dam 5 Water tree	South Dam		1
2020/09/28	11:00am	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		2

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/09/30	8:00am	Dam 5 Water tree	South Dam		1
2020/09/30	8:50am	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		2

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

[illegible]

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/10/03	7:50am	Dam 5 Water tree	South Dam		1
2020/10/03	9:40am	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		2

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/10/04	7:55am	Dam 5 Water tree	South Dam		1
2020/10/04	8:45am	Dam 5 Water tree		Ring Road	1
2020/10/04	9:30am	Dam 5 Water tree	South Dam		1
2020/10/04	10:15am	Dam 5 Water tree		Ring Road	1
2020/10/04	10:50am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/10/04	12:15pm	Dam 5 Water tree	South Dam		1
2020/10/04	1:00pm	Dam 5 Water tree		Ring Road	1
2020/10/04	1:50pm	Dam 5 Water tree	South Dam		1
2020/10/04	2:30pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/10/04	3:20pm	Dam 5 Water tree		Ring Road	1
2020/10/04	3:55pm	Dam 5 Water tree	South Dam		1
2020/10/04	5:00pm	Dam 5 Water tree	South Dam		1
2020/10/04	5:50pm	Dam 5 Water tree		Ring Road	1
2020/10/04	6:35pm	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		13

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/10/05	8:00am	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		1

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/10/06	7:55am	Dam 5 Water tree	South Dam		1
2020/10/06	9:00am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/10/06	12:20pm	Dam 5 Water tree	South Dam		1
2020/10/06	1:15pm	Dam 5 Water tree	South Dam		1
2020/10/06	2:50pm	Dam 5 Water tree		Ring Road	1
2020/10/06	4:10pm	Dam 5 Water tree	South Dam		1
2020/10/06	4:35pm	Dam 5 Water tree	South Dam		1
			TOTAL LOADS		7

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

[illegible]

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/10/08	8:00am	Dam 5 Water tree		Ring Road	1
2020/10/08	3:15pm	Dam 5 Water tree		Laydown 3 to mech tent	
			TOTAL LOADS		2

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: 20 000 (circle one) Litres/US Gallons	New Gold Area/Dept: Mine OPS
---------------	--	------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: 20 000	(circle one) Litres/US Gallons	New Gold Area/Dept: mine ops
------------------	---------------------------	-----------------------------------	---------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: mine ops
------------------	--------------------------	-----------------------------------	---------------------------------

[illegible]

On-call Phone: 807-632-6152

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: mine ops
------------------	--------------------------	-----------------------------------	---------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

V

Truck ID: 234

Truck Capacity: (circle one)
2000 Litres/US Gallons

New Gold Area/Dept:
Mine ops

1

741

Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: Mine OPS
------------------	--------------------------	-----------------------------------	---------------------------------

[illegible]

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: Mine Ops
------------------	--------------------------	-----------------------------------	---------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20 000	(circle one) Litres/US Gallons	New Gold Area/Dept: Mine OPS
-------------------------	----------------------------------	-----------------------------------	--

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/10/11	08:05	M F J	Copper N/S		1
"	10:05	"	Kal Tire Spot - copper n/s	Spot - AAG	1
"	12:05	"	Pit	PAG HR-8	1
"	5:05	"	Pit	PAG crusher	1
"	6:00	"		PAG	1

674 10206

newgold[™] Rainy River

April 16 - April 21 2020
2020 Water Application Form (v.01)

D Day Bob Hammond

2020 Water Application Form (v.01)

JR

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: Pit/Dump/TMA
------------------	--------------------------	-----------------------------------	-------------------------------------

Water Application Record

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

newgold™ Rainy River

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: NG MINCOPS
------------------	--------------------------	-----------------------------------	-----------------------------------

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Submit completed forms to:
New Gold RRM Environment
Department

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: 2000	(circle one) Litres/US Gallons	New Gold Area/Dept: mine ops
------------------	-------------------------	-----------------------------------	---------------------------------

Water Application Record

[illegible]

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID:	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept:
-----------	---	---------------------

[illegible]

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: 20000 (circle one) Litres/US Gallons	New Gold Area/Dept: Mine Ops
---------------	--	------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/04/25	8:20	Sump 4		Crusher/PAG SHR	1
"	9:30	"	Pit 603 Ramps	Crusher PAG	1
"	10:20	"	M60	PAG crusher	1
"	12:47	"		HR8	1
"	14:05	"	Pit 603	PAG/RB NWD	1
"	15:40	"	SPILL man	PAG/RB crusher	1
"	17:00	"	Pit 603	Crusher PAG	1

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20 000	(circle one) Litres/US Gallons	New Gold Area/Dept: Mine GPS
------------------	---------------------------	-----------------------------------	---------------------------------

[illegible]

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

^

8411

[illegible]

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: mine ops
-------------------------	--	--

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
20/04/27	7:30am	Sump 4		Road Base Chopper Area	1
20/04/27	8:30am	Sump 4		603 pit spellmans	1
20/04/27	10:30am	Sump 4		Fuel Bay TMA, Spellman	1
20/04/27	12:42	Sump 4		Base Rd Crusher, 603 pit	1
20/04/27	2:07	Sump 4		502 pit, 604 pit Base Rd south ramp	1
20/04/27	3:40	Sump 4		Spellmans TMA	1
20/04/27	4:37	Sump 4		604 pit m60, rd base	1
20/04/27	5:45	Sump 4	Filled up for	Next Shift	1
20/04/28	8:38	Sump 4		Chopper Flats Ramp South	1
20/04/28	10:00	Sump 4		TMA Spellman	1
20/04/28	11:00	Sump 4		Base Rd, 603	1
20/04/28	2:00	New tree (took long to fill)		TMA Spellman 602 pit	1
20/04/28	4:47	Sump 4		TMA, 602, Base Road, South Ramp	1

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept:
------------------	--	---------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
20/04/29	7:30 pm	Sump 4	Pit/Dump	Copper	1111 10
20/04/30	7:30 pm	? East out crop Sump 4	" "	"	1111
20/05/02	8:30 pm	Sump 4	" "	"	1111
20/05/03	7:15 pm	East out crop	" "	"	1111
20/05/04	7:15 pm	" "			1111
20/05/05	7:15 pm	" "	" "	" "	1111
20/05/06	7:15	East out crop	603/502, 0 wik-test fill	Copper Pit	1
	9:37	" "	" "	" "	1
	1:30	" "	" "	" "	1
	3:17	" "	" "	" "	1
	5:30				
06/05/20	8:00 pm	New Water Tree	Ramps, chopper	Pit 602,	1
06/05/20	10:30 pm	New Water Tree	Chopper	Chopper	1
06/05/20	12:00	New Water Tree	Pit		1
07/05/20	11:55	New Water Tree	Chopper		1

CCrew

ACrew

fuel gage Not working!

topped up @ 8:30 A.M

Submit completed forms to:
New Gold Rainy River Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

APR 11 - 6 - 2020

Всрв

Truck ID: 234

(circle one)
Litres/US Gallons

Water Application Record

AGew

On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: Mine ops
------------------	--	---------------------------------

[illegible]



Rainy River Project

Water Application and Truck Maintenance Form

Truck ID: 37-563	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
---------------------	----------------------------------	------------------------------------

Drivers Name: Scott Pippus	Date: June 2020-05-09
----------------------------	----------------------------------

Please circle one	Day Shift	Night Shift
-------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 9	Dam 5 Water Tree	111 3	South Dam Haul Road
May 9	Dam 5 Water Tree	111 3	Sig Crusher

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
New Gold RRP Environment Department

On-call Phone: 807-632-6152

3518

15AC

newgold

Rainy River

800 L

8690

2020 Water Application Form (v.01)

PM 20
Hyd Flwd

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: NEW Gold MINE ops
---------------	---	--

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020 5/9	8 AM	water tree	EOC	Pit roads Dump Roads	20,000
11 11	9.45	water Tree	EOC	" "	11 11
11 11	11:45	" "	" "	" "	11 11
20/5/9	2:05	water tree	EOC	" "	20,000
20/5/9	3:50	water tree	EOC	" "	20,000
20 5/9	6:10	water Tree	EOC	Pit Roads haul Roads	20,000
AGew NIGHTS 20/05/09	9:10 pm	Water tree	EOC	Chopper-Dump Roads	1
20/05/09	11:10 pm	Water tree	EOC	Pit, Camps.	1
20/05/10	1:00 am	Water tree	EOC	Creston Fuel Bay, Pit	1
20/05/10	3:07 am	Water tree	EOC	Chopper, Creston, Creston	1
20/05/10	5:10 am	Water tree	EOC	Truck, Fuel Bay	1

Submit completed forms to:
New Gold RRM Environment
Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

newgold™ Rainy River Project Water Application and Truck Maintenance Form

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
--------------------	----------------------------------	------------------------------------

Drivers Name: Scott P Date: ~~June~~ MAY 10

Please circle one Day Shift Night Shift

[illegible]

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Scott Pippus	Date: May 11/2020
----------------------------	-------------------

Please circle one	<input type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
-------------------	------------------------------------	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 11	Dam 5	6	South Dam Haul Road
May 11	Dam 5	3	SNL crusher

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 235	Truck Capacity: 20,000 (circle one) Litres/US Gallons	New Gold Area/Dept: NEW GOLD Mine ops
---------------	--	---------------------------------------

Water Application Record						
	Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
C crew	20/5/11	1:55 PM	water tree EOC	Pit Haul Rds	Roadway	1
	20/5/11	4:35 PM	1/ 1/	Pit Haul Rds	Roadway	1
AGew	20/05/11	7:47 PM	Water tree EOC	Pit Haul Rds	Roadways	1
	20/05/11	9:50 PM	Water tree EOC	Pit Tma	Roadways	1
	20/05/11	11:55 PM	Water tree EOC	Pit Tma	Roadways	1
	20/05/12	1:50 am	Water tree EOC	Pit TMA	Roadways	1
	20/05/12	4:00 am	Water Tree EOC	Pit TMA Red Dump	"	1
C crew	20/05/12	7:30 AM	water tree EOC	Pit TMA Red Dump	Roadways	1
	20/05/12	9:45 AM	water tree EOC	Pit TMA Red Dump	Roadways	1
	20/05/12	1:30 PM	water tree EOC	Pit TMA Red dump	Roadways	1
	20/05/12	3:30 PM	water tree EOC	Pit TMA Red dump	Roadways	1
	20/05/12	5:05 PM	water tree EOC	Pit TMA Red dump	Roadways	1
AGew NIGHTS	20/05/12	8:00 PM	Water Tree EOC	TMA Red dump	Roadways	1
	20/05/12	10:08 PM	water tree EOC	TMA Pit, Red	Roadways	1
	20/05/13	12:08 AM	Water Tree EOC	TMA, Red, Pit	Roadways	1

8735.2
700 L

Submit completed forms to:
New Gold BRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

~~4703.5~~
8759.5
760 L

2020 Water Application Form (v.01)

Truck ID: 235	Truck Capacity: 20000 (circle one) Litres/US Gallons	New Gold Area/Dept: New Gold Mine ops
---------------	--	---------------------------------------

Water Application Record

[illegible]

Accu
NIGHTS

Submit completed forms to:
New Gold RRM Environment
Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: Mine 400
------------------	---	---------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 16/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 16	Dam 5 Water tree	4	South Dam
May 16	Dam 5 Water tree	5.5	Haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Brew
Bret McQuaker

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: Mine Ops
---------------	---	---------------------------------

Submit completed forms to:
New Gold RRM Environment
Department
rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper	Date: May 17/2020
---------------------------	-------------------

Please circle one	Day Shift	Night Shift
-------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 17	Dam 5 Water tree	1	South Dam

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 17/2020
----------------------------	-------------------

<u>Please circle one</u>	<u>Day Shift</u>	Night Shift
--------------------------	------------------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 17	Dam 5 Water tree	3	South Dam
May 17	Dam 5 Water tree	2	Haul roads
May 17	Dam 5 Water tree	4	Ring road
May 17	Dam 5 Water tree	2	Haul to lay down

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 18/2020
----------------------------	-------------------

<i>Please circle one</i>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 18	Dam 5 Water tree	4	South Dam
May 18	Dam 5 Water tree	1	Haul roads
May 18	Dam 5 Water tree	5	Ring road
May 18	Dam 5 Water tree	2	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainriver.enviro@newgold.com
 On-call Phone: 807-632-6152

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper	Date: May 18/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 18	Dam 5 Water tree	3	South Dam/Haul roads
May 18	Dam 5 Water tree	2	North Dam/haul roads near laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503/4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 19/2020
----------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 19	Dam 5 Water tree	2 (using 4-504) 2 (using 4-252)	South Dam
May 19	Dam 5 Water tree	1 (using 4-504) 1 (using 4-252)	Haul roads
May 19	Dam 5 Water tree	2 (using 4-504)	SNL crusher
May 19	Dam 5 Water tree	1 (using 4-504)	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com



Rainy River Project

Water Application and Truck Maintenance Form

Truck ID: 4-504	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper/Brett Brown	Date: May 19/2020
---------------------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 19	Dam 5 Water tree	2	South Dam core
May 19	Dam 5 Water tree	1	South Dam core and haul road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
New Gold RRP Environment Department
Rainriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Mike Klippenstein	Date: May 20/2020
---------------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 20	Dam 5 Water tree	3	South Dam core
May 20	Dam 5 Water tree	2	haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503/4-503

Truck Capacity:

20,000 Liters

Contractor: Sigfusson Northern Ltd

Drivers Name: Kevin Ciemny

Date: May 20/2020

Please circle one

☒ Day Shift

☐ Night Shift

Water Application Record

Date	Water Source	Number of Full Loads	Watering Locations
May 20	Dam 5 Water tree	1 (using 4-504) 3 (using 4-503)	South Dam
May 20	Dam 5 Water tree	3 (using 4-503)	Haul roads
May 20	Dam 5 Water tree	1 (using 4-503)	SNL crusher
May 20	Dam 5 Water tree	2 (using 4-503)	SNL mechanic tent to laydown 3
May 20	Dam 5 Water tree	3 (using 4-503)	Ring roads

Water Truck Maintenance and Repair Record

Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:

New Gold RRP Environment Department

Rainyriver.enviro@newgold.com

Truck ID: 234	Truck Capacity: 20,000 (circle one) Litres/US Gallons	New Gold Area/Dept: New Gold
---------------	---	------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
20/5/20		EOC water tree	PIT Haul Rd 3	Roads	1
20/5/20		EOC water tree	PIT Copper Flats TMA	Roadways	1
20/5/20		EOC water tree	PIT Haul Rd 3 TMA	Roadways	1
20/5/20		EOC water tree	PIT Pumps South H H R	Roadways	1
20/5/20		EOC water tree	PIT Copper cut across	Roadways	1
20/5/20		EOC water tree	PIT Dumps Haul Rds	Roadways	1
20/5/21		EOC water tree	PIT Dumps Haul Rds	Roadways	1
20/5/21		EOC water tree	PIT Dumps Haul Rds	Roadways	1
20/5/21		EOC water tree	PIT Dumps Haul Rds	Roadways	1
20/5/21		EOC water tree	PIT Dumps Haul Rds	Roadways	1
20/5/21		EOC water tree	PIT Dumps Haul Rds	Roadways	1
20/5/21		EOC water tree	PIT Dumps Haul Rds	Roadway	1

C
Crew
↓
Crew
C
Crew

1 98793.1

873.1

750 L

1035 L

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 21/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 21	Dam 5 Water tree	5	South Dam
May 21	Dam 5 Water tree	3	Haul roads
May 21	Dam 5 Water tree	1	SNL crusher
May 21	Dam 5 Water tree	2	SNL mechanic tent to laydown 3
May 21	Dam 5 Water tree	4	Ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Brett Brown	Date: May 21/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 21	Dam 5 Water tree	2.5	South Dam core/haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: Mine Ops C-crew
------------------	--	--

[illegible]

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-503/4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 22/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 22	Dam 5 Water tree	2 (using 4-503) 1 (using 4-252)	South Dam
May 22	Dam 5 Water tree	1 (using 4-503) 1 (using 4-252)	Haul roads
May 22	Dam 5 Water tree	1 (using 4-252)	SNL crusher
May 22	Dam 5 Water tree	1 (using 4-252) 1 (using 4-503)	SNL mechanic tent to laydown 3
May 22	Dam 5 Water tree	2 (using 4-252) 2 (using 4-503)	Ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 23/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 23	Dam 5 Water tree	2	South Dam
May 23	Dam 5 Water tree	1	Haul roads
May 23	Dam 5 Water tree	0.5	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: Nights MineOPS C-Crew
------------------	---	--

[illegible]

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: Mine OPS
------------------	--------------------------	-----------------------------------	---------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Brett Brown	Date: May 23/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 23	Dam 5 Water tree	1	South Dam core/haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 24/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 24	Dam 5 Water tree	2	South Dam
May 24	Dam 5 Water tree	1	Haul roads
May 24	Dam 5 Water tree	2	SNL mechanic tent to laydown 3 and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: Mine OPS
-------------------------	---------------------------------	-----------------------------------	--

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/05/24	07:50	water tree	Pit	Pag Copper N/S	1
"	09:30	"	Pit 603		1
"	12:00	"		Copper N/S	1
"	14:45	"		Pag/crusher Copper N	1
"	15:10	"	601/603 Pit	crusher Pag	1
"	16:35	"		Copper N/S	1
"	17:45	"	601 Pit	PAG Copper N	1

89161

Submit completed forms to:
New Gold RRM Environment
Department

Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

DX13KA BK
Host

DJF1KA TM

1206

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: MINE OPS.
------------------	--	----------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department

Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

newgoldTM Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-252/4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 25/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 25	Dam 5 Water tree	4 (using 4-252)	South Dam
May 25	Dam 5 Water tree	1 (using 4-251)	SNL mechanic tent to laydown 3
May 25	Dam 5 Water tree	2 (using 4-252) 1 (using 4-251)	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: (circle one) 20000 Litres/US Gallons	New Gold Area/Dept: NEW Gold
---------------	---	------------------------------

Water Application Record

[illegible]

Crew

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Scott Pippus	Date: May 27/2020
----------------------------	-------------------

<i>Please circle one</i>	Day Shift	Night Shift
--------------------------	------------------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 27	Dam 3	4	South Dam
May 27	Dam 3	1	SNL mechanic tent to laydown 3
May 27	Dam 3	2	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: <i>[Signature]</i>
----------------------	---	--

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
20/05/27	7:15pm	EOC	Mine Pit/Dumps/Fuel Bay	Pag Road	
20/05/28	7:30am	EOC	Pit Surroundings	Road/Water	
20/05/28	7:15pm	"	"	"	
20/05/29	7:30am	"	"	"	
20/05/29	10:00pm	"	"	"	
20/05/30	8:00am	"	"	"	
20/05/30	11:00pm	"	"	"	
20/05/31	8:00am	"	"	"	
20/05/31	9:19pm	"	"	"	
20/06/01	8:00am	"	"	"	
20/06/01	7:15pm	"	"	"	
20/06/02	7:30	"	"	"	

Submit completed forms to:
New Gold RRM Environment
Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

newgold™ Rainy River Project Water Application and Truck Maintenance Form

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Scott Pippus	Date: May 28/2020
----------------------------	-------------------

<i>Please circle one</i>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 28	Dam 3	3	South Dam
May 28	Dam 3	1	SNL mechanic tent to laydown 3
May 28	Dam 3	1	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152



Rainy River Project

Water Application and Truck Maintenance Form

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Trevor Bailey	Date: May 29/2020
-----------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 29	Dam 3	3	South Dam clay core

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 7-563	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
---------------------------	-------------------------------	------------------------------------

Drivers Name: Scott Phipps	Date: June 2020-05-09
-----------------------------------	------------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 9	Dam 5 Water Tree	113	South Dam Haul Road
May 9	Dam 5 Water Tree	113	Sig Crusher

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
---------------------------	----------------------------------	------------------------------------

Drivers Name: Scott P	Date: June MAY 10
------------------------------	-------------------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 10	Dam 5	111 3	SOUTH DAM HAUL ROADS
May 10	Dam 5	1 1	SIS CRUSHER

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
New Gold RRP Environment Department

On-call Phone: 807-532-6152

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Scott Pippus	Date: May 11/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 11	Dam 5	6	South Dam Haul Road
May 11	Dam 5	3	SNL crusher

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 16/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 16	Dam 5 Water tree	4	South Dam
May 16	Dam 5 Water tree	5.5	Haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Kevin Ciemny	Date: May 17/2020
----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 17	Dam 5 Water tree	3	South Dam
May 17	Dam 5 Water tree	2	Haul roads
May 17	Dam 5 Water tree	4	Ring road
May 17	Dam 5 Water tree	2	Haul to lay down

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper	Date: May 17/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 17	Dam 5 Water tree	1	South Dam

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 18/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 18	Dam 5 Water tree	4	South Dam
May 18	Dam 5 Water tree	1	Haul roads
May 18	Dam 5 Water tree	5	Ring road
May 18	Dam 5 Water tree	2	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Ross Cooper	Date: May 18/2020
----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 18	Dam 5 Water tree	3	South Dam/Haul roads
May 18	Dam 5 Water tree	2	North Dam/haul roads near laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503/4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 19/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 19	Dam 5 Water tree	2 (using 4-504) 2 (using 4-252)	South Dam
May 19	Dam 5 Water tree	1 (using 4-504) 1 (using 4-252)	Haul roads
May 19	Dam 5 Water tree	2 (using 4-504)	SNL crusher
May 19	Dam 5 Water tree	1 (using 4-504)	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

On-call Phone: 807-632-6152

Truck ID: 4-504	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Ross Cooper/Brett Brown	Date: May 19/2020
---------------------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 19	Dam 5 Water tree	2	South Dam core
May 19	Dam 5 Water tree	1	South Dam core and haul road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503/4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 20/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 20	Dam 5 Water tree	1 (using 4-504) 3 (using 4-503)	South Dam
May 20	Dam 5 Water tree	3 (using 4-503)	Haul roads
May 20	Dam 5 Water tree	1 (using 4-503)	SNL crusher
May 20	Dam 5 Water tree	2 (using 4-503)	SNL mechanic tent to laydown 3
May 20	Dam 5 Water tree	3 (using 4-503)	Ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

On-call Phone: 807-632-6152

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Mike Klippenstein	Date: May 20/2020
---------------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 20	Dam 5 Water tree	3	South Dam core
May 20	Dam 5 Water tree	2	haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 21/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 21	Dam 5 Water tree	5	South Dam
May 21	Dam 5 Water tree	3	Haul roads
May 21	Dam 5 Water tree	1	SNL crusher
May 21	Dam 5 Water tree	2	SNL mechanic tent to laydown 3
May 21	Dam 5 Water tree	4	Ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Brett Brown	Date: May 21/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 21	Dam 5 Water tree	2.5	South Dam core/haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-503/4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 22/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 22	Dam 5 Water tree	2 (using 4-503) 1 (using 4-252)	South Dam
May 22	Dam 5 Water tree	1 (using 4-503) 1 (using 4-252)	Haul roads
May 22	Dam 5 Water tree	1 (using 4-252)	SNL crusher
May 22	Dam 5 Water tree	1 (using 4-252) 1 (using 4-503)	SNL mechanic tent to laydown 3
May 22	Dam 5 Water tree	2 (using 4-252) 2 (using 4-503)	Ring roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 23/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 23	Dam 5 Water tree	2	South Dam
May 23	Dam 5 Water tree	1	Haul roads
May 23	Dam 5 Water tree	0.5	SNL mechanic tent to laydown 3

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Brett Brown	Date: May 23/2020
---------------------------	-------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	-----------	-------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 23	Dam 5 Water tree	1	South Dam core/haul roads

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-252	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 24/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 24	Dam 5 Water tree	2	South Dam
May 24	Dam 5 Water tree	1	Haul roads
May 24	Dam 5 Water tree	2	SNL mechanic tent to laydown 3 and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 4-252/4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------------	--------------------------------------	---

Drivers Name: Kevin Ciemny	Date: May 25/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 25	Dam 5 Water tree	4 (using 4-252)	South Dam
May 25	Dam 5 Water tree	1 (using 4-251)	SNL mechanic tent to laydown 3
May 25	Dam 5 Water tree	2 (using 4-252) 1 (using 4-251)	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Scott Pippus	Date: May 27/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 27	Dam 3	4	South Dam
May 27	Dam 3	1	SNL mechanic tent to laydown 3
May 27	Dam 3	2	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
------------------------	--------------------------------------	---

Drivers Name: Scott Pippus	Date: May 28/2020
-----------------------------------	--------------------------

<u>Please circle one</u>	Day Shift	Night Shift
--------------------------	------------------	--------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 28	Dam 3	3	South Dam
May 28	Dam 3	1	SNL mechanic tent to laydown 3
May 28	Dam 3	1	Haul roads and ring road

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Truck ID: 4-251	Truck Capacity: 20,000 Liters	Contractor: Sigfusson Northern Ltd
-----------------	-------------------------------	------------------------------------

Drivers Name: Trevor Bailey	Date: May 29/2020
-----------------------------	-------------------

<u>Please circle one</u>	<input checked="" type="checkbox"/> Day Shift	<input type="checkbox"/> Night Shift
--------------------------	---	--------------------------------------

Water Application Record			
Date	Water Source	Number of Full Loads	Watering Locations
May 29	Dam 3	3	South Dam clay core

Water Truck Maintenance and Repair Record	
Please Check	Description of Repair, Servicing or Routine Maintenance
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Daily Truck Inspection

Submit completed forms to:
 New Gold RRP Environment Department
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: <i>234 Water truck</i>	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: <i>Mine Ops</i>
-------------------------------------	--	--

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
20/06/02	7:10pm	EOC	Mine area	Truck Pug Road Haul Road 1	11
20/06/03	8:00AM	11	11	11	11
20/06/04	7:30AM	11	11	11	11
20/06/05	8:00AM	11	11	11	11
20/06/06	7:30AM	11	11	11	11
20/06/06	9:43pm	EOC	EOC, water tree	Pit, Copper	1
20/06/06	11:43pm	EOC	Water/pu	Img, pit	1
20/06/07	1:14am	EOC	Water/pu	Chopper	1
20/06/07	3:29am	EOC	Water/pu		1
20/06/08	7:12pm	EOC	Water/pu	Steakway Way	1
20/06/08	8:30pm	EOC	Water/pu		1

got 1/2 water
fuel @ left
at 3:00am

(A crew)
NIGHT
SHIFT

ACrew
N-S.

2020 Water Application Form (v.01)

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: Mine ops
------------------	---	---------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department

On-call Phone: 807-632-6152

[illegible]

On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20 000	(circle one) Litres/US Gallons	New Gold Area/Dept: ADD:nc OPS
-------------------------	----------------------------------	-----------------------------------	--

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/17	08:14	Malf. Junct.	Pit		1
"	09:10	"		PAG South copper	1
"	10:20	"	Pit 602/3		1
"	11:55	"	Pit 602/3		1
"	12:50	"		PAG South copper	1
"	13:55	"	Pit Rom	Crusher	1
"	14:55	"		PAG/South copper	1
"	16:30	"	Pit		1/2
"	17:10	"	Pit		1
"	18:00	"		PAG/South copper	1

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	New Gold Area/Dept: Mine Ops
-------------------------	---------------------------------	-----------------------------------	--

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/19	7:40	Mal. J uact	Pit		1
"	8:50	"		PAG - copper south	1
"	10:45	"	Pit	Pag C IV P. 9th	1
"	11:40	"	Pit	PAG copper	1
"	12:50	"		PAG copper N/S crusher	1
"	13:59	"	504 Pit	Pag / copper south	1
"	15:35	"		Pag / copper north	1
"	16:45	"	Pit Ramps	crusher	1
"	17:55	"		PAG copper south	1

9342

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20 000 (circle one) Litres/US Gallons	New Gold Area/Dept: Mine ops
---------------	--	------------------------------

[illegible]

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: Mine Ops
---------------	---	------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/24	9:00 AM	Malfunction Junction	Pits/roads		6
2020/06/24	7:30 PM			Ramps/Haul Roads	(6)
2020/06/25	7:40 AM				10
2020/06/25	7:18 PM				(5)
2020/06/26	7:50 AM				9
2020/06/26	7:20 AM				
2020/06/26	7:20 PM				(3)
2020/06/27	7:20 AM				11
2020/06/27					
2020/06/27	7:10 PM				(4)
2020/06/28	7:20 AM				12
2020/06/28	7:10 PM				(7)
2020/06/28	7:23 AM				8
2020/06/29	8:30				(4)
2020/06/30	10:00 AM				7
2020/06/30	7:10 PM				

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/06/25	8:00am	Dam 5 Water tree	South Dam Clay Core		1
2020/06/25	8:35am	Dam 5 Water tree		Haul Road 13	1
2020/06/25	9:25am	Dam 5 Water tree		Ring Road	1
2020/06/25	10:40am	Dam 5 Water tree		Haul Road 13	1
2020/06/25	11:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/06/25	11:20am	Dam 5 Water tree		Ring Road	1
2020/06/25	12:40pm	Dam 5 Water tree		Haul Road 13	1
2020/06/25	12:55pm	Dam 5 Water tree		Laydown 3 to mech tent	1
			TOTAL LOADS		8

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/02	3:00pm	Dam 5 Water tree	South Dam Clay core		1
2020/07/02	3:30pm	Dam 5 Water tree		South Dam haul road	1
2020/07/02	4:15pm	Dam 5 water tree		Ring Road	1
2020/07/02	4:50pm	Dam 5 Water tree	South Dam Clay core		1
2020/07/02	5:40pm	Dam 5 Water tree		South Dam haul road	1
2020/07/02	6:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/02	10:30pm	Dam 5 Water tree	South Dam Clay core		1
2020/07/02	11:10pm	Dam 5 Water tree		South Dam haul road	1
2020/07/02	11:45pm	Dam 5 Water tree		Ring Road	1
2020/07/02	12:25am	Dam 5 Water tree		South Dam haul road	1
2020/07/02	12:50am	Dam 5 Water tree		South Dam haul road	1
2020/07/02	2:00am	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		12

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/02	2:30pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/02	3:10pm	Dam 5 Water tree		Haul Road	1
2020/07/02	3:55pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/02	4:35pm	Dam 5 Water tree		Haul Road	1
2020/07/02	5:50pm	Dam 5 Water tree		Haul Road	1
2020/07/02	6:40pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		6

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/03	8:00am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/03	8:45am	Dam 5 Water tree		Haul Road	1
2020/07/03	9:40am	Dam 5 Water tree		Haul Road	1
2020/07/03	10:35am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/03	11:10am	Dam 5 Water tree		Ring Road	1
2020/07/03	12:50pm	Dam 5 Water tree		Haul Road	1
2020/07/03	4:35pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/03	5:35pm	Dam 5 Water tree		Ring Road	1
2020/07/03	6:40pm	Dam 5 Water tree		Haul Road	1
2020/07/03	7:55pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/03	8:40pm	Dam 5 Water tree		Ring Road	1
2020/07/03	1:45am	Dam 5 Water tree		Haul Road	1
			TOTAL LOADS		12

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/03	8:00am	Dam 5 Water tree	South Dam Clay core		1
2020/07/03	8:40am	Dam 5 Water tree		Ring Road	1
2020/07/03	9:15am	Dam 5 water tree		Haul Road	1
2020/07/03	9:50am	Dam 5 Water tree	South Dam Clay core		1
2020/07/03	10:30am	Dam 5 Water tree		Laydown 3 to Mech Tent	1
2020/07/03	11:15am	Dam 5 Water tree		Haul Road	1
2020/07/03	11:50am	Dam 5 Water tree	South Dam Clay core		1
2020/07/03	12:40pm	Dam 5 Water tree		Haul Road	1
2020/07/03	1:20pm	Dam 5 Water tree		Ring Road	1
2020/07/03	2:25pm	Dam 5 Water tree	South Dam Clay core		1
			TOTAL LOADS		10

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/04	8:05am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/04	8:45am	Dam 5 Water tree		Ring Road	1
2020/07/04	9:35am	Dam 5 Water tree		Haul Road	1
2020/07/04	10:25am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/04	11:15am	Dam 5 Water tree		Ring Road	1
2020/07/04	11:55am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/04	12:25pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/04	1:15pm	Dam 5 Water tree		Haul Road	1
2020/07/04	2:05pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/04	3:00pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/04	3:35pm	Dam 5 Water tree		Haul Road	1
2020/07/04	4:20pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/04	5:15pm	Dam 5 Water tree		Ring Road	1
2020/07/04	5:50pm	Dam 5 Water tree		Haul Road	1
2020/07/04	6:30pm	Dam 5 Water tree		Ring Road	1
2020/07/04	8:00pm	Dam 5 Water tree		South Dam Haul Road	1
2020/07/04	9:05pm	Dam 5 Water tree		Ring Road	1
2020/07/04	6:40am	Dam 5 Water tree		Laydown 3 to mech tent	1
			TOTAL LOADS		18

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/05	8:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/05	8:55am	Dam 5 Water tree		Ring Road	1
2020/07/05	9:40am	Dam 5 Water tree		Haul Road	1
2020/07/05	10:35am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/05	11:15am	Dam 5 Water tree		Ring Road	1
2020/07/05	12:05pm	Dam 5 Water tree		Haul Road	1
2020/07/05	12:45pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/05	1:45pm	Dam 5 Water tree		Ring Road	1
2020/07/05	2:35pm	Dam 5 Water tree	South Dam Clay Core		1
			TOTAL LOADS		9

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/06	12:15pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/06	1:10pm	Dam 5 Water tree		Ring Road	1
2020/07/06	1:55pm	Dam 5 Water tree		Haul Road	1
2020/07/06	2:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/06	3:05pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/06	3:55pm	Dam 5 Water tree		Ring Road	1
2020/07/06	4:45pm	Dam 5 Water tree		Haul Road	1
2020/07/06	5:35pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/06	6:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/06	8:00pm	Dam 5 Water tree		South Dam Haul Road	1
2020/07/06	8:40pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/06	9:30pm	Dam 5 Water tree		Ring Road	1
2020/07/06	11:00pm	Dam 5 Water tree		Haul Road 3	1
2020/07/06	12:15am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/06	1:30am	Dam 5 Water tree		Ring Road	1
2020/07/06	3:00am	Dam 5 Water tree		Ring Road	1
2020/07/06	4:15am	Dam 5 Water tree		Haul Road 3	1
2020/07/06	5:10am	Dam 5 Water tree	South Dam Clay Core		1
			TOTAL LOADS		18

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	Contractor: New Gold
------------------	--------------------------	-----------------------------------	-------------------------

[illegible]

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/07	8:20am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/07	9:05am	Dam 5 Water tree		Ring Road	1
2020/07/07	9:45am	Dam 5 Water tree		Haul Road	1
2020/07/07	10:20am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/07	11:15am	Dam 5 Water tree		Haul Road	1
2020/07/07	11:52am	Dam 5 Water tree		Ring Road	1
2020/07/07	12:30pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/07	1:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/07	2:05pm	Dam 5 Water tree		Haul Road	1
2020/07/07	3:00pm	Dam 5 Water tree		Ring Road	1
2020/07/07	4:55pm	Dam 5 Water tree		Haul Road	1
2020/07/07	5:35pm	Dam 5 Water tree		Haul Road	1
2020/07/07	6:25pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/07	8:00pm	Dam 5 Water tree		Haul Road 8	1
2020/07/07	8:35pm	Dam 5 Water tree		Ring Road	1
2020/07/07	9:10pm	Dam 5 Water tree		Ring Road	1
2020/07/07	9:35pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/07	10:20pm	Dam 5 Water tree		Haul Road 8	1
2020/07/07	4:55am	Dam 5 Water tree		Ring Road	1
2020/07/07	5:30am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/07	6:10am	Dam 5 Water tree		Haul Road 8	1
2020/07/07	6:45am	Dam 5 Water tree	South Dam Clay Core		1
			TOTAL LOADS		22

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/08	9:35am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/08	10:30am	Dam 5 Water tree		Ring Road	1
2020/07/08	11:15am	Dam 5 Water tree		Haul Road	1
2020/07/08	12:05pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/08	12:55pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/08	1:40pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/08	2:50pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/08	3:35pm	Dam 5 Water tree		Ring Road	1
2020/07/08	4:45pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/08	5:25pm	Dam 5 Water tree		Haul Road	1
2020/07/08	6:20pm	Dam 5 Water tree		Ring Road	1
2020/07/08	7:55pm	Dam 5 Water tree		Haul Road	1
2020/07/08	8:30pm	Dam 5 Water tree		Ring Road	1
2020/07/08	9:05pm	Dam 5 Water tree		Haul Road 8	1
2020/07/08	9:35pm	Dam 5 Water tree		Haul Road	1
2020/07/08	10:05pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		16

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/09	8:15am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/09	10:25am	Dam 5 Water tree		Ring Road	1
2020/07/09	11:05am	Dam 5 Water tree		Haul Road	1
2020/07/09	11:45am	Dam 5 Water tree		Haul Road	1
2020/07/09	12:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/09	1:35pm	Dam 5 Water tree		Ring Road	1
2020/07/09	2:45pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/09	3:40pm	Dam 5 Water tree		Haul Road	1
2020/07/09	4:35pm	Dam 5 Water tree		Ring Road	1
2020/07/09	5:30pm	Dam 5 Water tree		Haul Road	1
2020/07/09	6:25pm	Dam 5 Water tree		Ring Road	1
2020/07/09	8:05pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/09	8:30pm	Dam 5 Water tree		Haul Road 8	1
2020/07/09	9:15pm	Dam 5 Water tree		Ring Road	1
2020/07/09	9:55pm	Dam 5 Water tree		Dam 5 Haul Road	1
			TOTAL LOADS		15

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/10	8:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/10	9:55am	Dam 5 Water tree		Ring Road	1
2020/07/10	10:30am	Dam 5 Water tree		Haul Road	1
2020/07/10	11:20am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/10	12:10pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/10	12:55pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/10	1:45pm	Dam 5 Water tree		Ring Road	1
2020/07/10	2:45pm	Dam 5 Water tree		Haul Road	1
2020/07/10	4:20pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/10	5:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/10	6:05pm	Dam 5 Water tree		Haul Road	1
2020/07/10	6:45pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/10	7:50pm	Dam 5 Water tree		Ring Road	1
2020/07/10	8:30pm	Dam 5 Water tree		Haul Road	1
			TOTAL LOADS		14

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/10	8:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/10	8:50am	Dam 5 Water tree		Ring Road	1
2020/07/10	9:30am	Dam 5 Water tree		Laydown to mech tent	1
2020/07/10	10:10am	Dam 5 Water tree		Haul Road	1
2020/07/10	11:05am	Dam 5 Water tree		Ring Road	1
2020/07/10	11:35am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/10	12:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/10	1:35pm	Dam 5 Water tree		Ring Road	1
2020/07/10	2:20pm	Dam 5 Water tree		Haul Road	1
2020/07/10	3:10pm	Dam 5 Water tree		Ring Road	1
2020/07/10	4:10pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/10	5:00pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/10	5:55pm	Dam 5 Water tree		Ring Road	1
2020/07/10	4:30am	Dam 5 Water tree		Haul Road	1
2020/07/10	5:30am	Dam 5 Water tree	South Dam Clay Core		1
			TOTAL LOADS		15

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/11	8:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/11	11:55am	Dam 5 Water tree		Ring Road	1
2020/07/11	12:55pm	Dam 5 Water tree		Haul Road	1
2020/07/11	1:45pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/11	2:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/11	3:55pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/11	4:35pm	Dam 5 Water tree		Ring Road	1
2020/07/11	5:20pm	Dam 5 Water tree		Haul Road	1
2020/07/11	6:05pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/11	6:35pm	Dam 5 Water tree		Haul Road	1
2020/07/11	11:45pm	Dam 5 Water tree		Ring Road	1
2020/07/11	12:20am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/11	1:05am	Dam 5 Water tree		Haul Road	1
2020/07/11	1:45am	Dam 5 Water tree		Haul Road	1
			TOTAL LOADS		14

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-503	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/14	2:10pm	Dam 5 Water tree		Ring Road	1
2020/07/14	2:55pm	Dam 5 Water tree		Haul Road	1
2020/07/14	3:55pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/14	4:20pm	Dam 5 Water tree		Ring Road	1
2020/07/14	5:00pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/14	5:40pm	Dam 5 Water tree		Haul Road	1
2020/07/14	6:10pm	Dam 5 Water tree		Ring Road	1
2020/07/14	6:45pm	Dam 5 Water tree		Haul Road	1
2020/07/14	8:05pm	Dam 5 Water tree		Haul Road 8	1
2020/07/14	8:35pm	Dam 5 Water tree		South Dam Haul Road	1
2020/07/14	9:20pm	Dam 5 Water tree		Ring Road	1
2020/07/14	10:00pm	Dam 5 Water tree		West Dam Haul Road	1
2020/07/14	11:30pm	Dam 5 Water tree		South Dam Haul Road	1
2020/07/14	1:00am	Dam 5 Water tree		Ring Road	1
2020/07/14	2:35am	Dam 5 Water tree		Haul Road 8	1
2020/07/14	3:55am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/14	4:35am	Dam 5 Water tree		Ring Road	1
2020/07/14	5:45am	Dam 5 Water tree	South Dam Clay Core		1
			TOTAL LOADS		18

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20 000	(circle one) Litres/US Gallons	Contractor: New Gold
------------------	---------------------------	-----------------------------------	-------------------------

[illegible]

9697 time

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/15	8:00am	Dam 5 Water tree		Ring Road	1
2020/07/15	8:40am	Dam 5 Water tree		Haul Road	1
2020/07/15	9:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/15	9:55am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/15	10:30am	Dam 5 Water tree		Ring Road	1
2020/07/15	11:20am	Dam 5 Water tree		Haul Road	1
2020/07/15	11:50am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/15	12:30pm	Dam 5 Water tree		Haul Road	1
2020/07/15	1:10pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/15	2:35pm	Dam 5 Water tree		Ring Road	1
2020/07/15	3:10pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/15	3:45pm	Dam 5 Water tree		Haul Road	1
2020/07/15	4:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/15	5:25pm	Dam 5 Water tree		Haul Road	1
2020/07/15	5:55pm	Dam 5 Water tree		Ring Road	1
2020/07/15	6:40pm	Dam 5 Water tree	South Dam Clay Core		1
			TOTAL LOADS		16

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20 000	(circle one) Litres/US Gallons	Contractor: New Gold
------------------	---------------------------	-----------------------------------	-------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

784 8016

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/16	8:05am	Dam 5 Water tree		Ring Road	1
2020/07/16	8:35am	Dam 5 Water tree		Haul Road	1
2020/07/16	9:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/16	9:35am	Dam 5 Water tree		Ring Road	1
2020/07/16	10:25am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/16	11:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/16	12:00pm	Dam 5 Water tree		Haul Road	1
2020/07/16	12:40pm	Dam 5 Water tree		Ring Road	1
2020/07/16	1:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/16	1:45pm	Dam 5 Water tree		Haul Road	1
2020/07/16	2:30pm	Dam 5 Water tree	South Dam Clay Core		1
2020/07/16	3:50pm	Dam 5 Water tree		Ring Road	1
2020/07/16	4:25pm	Dam 5 Water tree		Haul Road	1
2020/07/16	5:10pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/16	5:50pm	Dam 5 Water tree		Ring Road	1
2020/07/16	6:40pm	Dam 5 Water tree		Ring Road	1
2020/07/16	8:30pm	Dam 5 Water tree		Haul Road 8	1
2020/07/16	9:15pm	Dam 5 Water tree		Ring Road	1
2020/07/16	10:20pm	Dam 5 Water tree		South Dam Haul Road	1
2020/07/16	11:35pm	Dam 5 Water tree		North Dam Haul Road	1
2020/07/16	12:15am	Dam 5 Water tree		Ring Road	1
2020/07/16	12:50am	Dam 5 Water tree		South Dam Haul Road	1
2020/07/16	1:20am	Dam 5 Water tree		Haul Road 8	1
2020/07/16	3:00am	Dam 5 Water tree		Ring Road	1
2020/07/16	4:35am	Dam 5 Water tree		North Dam Haul Road	1
2020/07/16	5:10am	Dam 5 Water tree		South Dam Haul Road	1
2020/07/16	5:45am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/16	6:25am	Dam 5 Water tree		Ring Road	1
2020/07/16	7:00am	Dam 5 Water tree		Haul Road 8	1
TOTAL LOADS					28

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.

Truck ID: 234	Truck Capacity: 20000	(circle one) Litres/US Gallons	Contractor: New Gold
-------------------------	---------------------------------	-----------------------------------	--------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/17	7:45	MFS	Copper	PAG	1
"	8:40	"	Copper South		1
"	9:55	"	Copper N/S	PAG	1
"	11:00	"	Pit	SHR HR8 PAG	1
"	12:00	"	Pit	PAG	1
"	13:20	PAG Road W.T.	Copper S/N	PAG	1
"	14:30	"		South HR PHR8	1
"	16:00	"	Copper N/S	PAG	1
"	17:35	"	Copper N/S	PAG	1

925
9724

Truck ID: 234	Truck Capacity: 2000	(circle one) Litres/US Gallons	Contractor: New Gold
-------------------------	--------------------------------	-----------------------------------	--------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/17	08:00	MFS waterline	Copper S	PAG cluster	1
"	9:10	"	"	"	1
"	10:25	"	Pit	PAG	1
"	11:35	"	Copper N/S	PAG	1
"	12:30	"	Pit Copper N	PAG	1
"	13:45	"	Copper N/S	PAG	1
"	14:55	"		PAG cluster	1
"	16:00	"			1
"	17:05	"	Copper S	PAG	1
"	18:10	"	Pit	MR8/SRH	1

9738

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/17	8:00am	Dam 5 Water tree		North Dam Haul Road	1
2020/07/17	8:25am	Dam 5 Water tree		Ring Road	1
2020/07/17	9:00am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/17	9:35am	Dam 5 Water tree		Haul Road	1
2020/07/17	10:10am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/17	10:45am	Dam 5 Water tree		Ring Road	1
2020/07/17	11:55am	Dam 5 Water tree		Haul Road	1
2020/07/17	12:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/17	1:05pm	Dam 5 Water tree		Ring Road	1
2020/07/17	1:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/17	2:35pm	Dam 5 Water tree		Haul Road	1
2020/07/17	3:55pm	Dam 5 Water tree		Ring Road	1
2020/07/17	5:00pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/17	5:40pm	Dam 5 Water tree		Haul Road	1
2020/07/17	6:25pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		15

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/18	8:15am	Dam 5 Water tree		Ring Road	1
2020/07/18	8:45am	Dam 5 Water tree		Haul Road	1
2020/07/18	9:15am	Dam 5 Water tree		Haul Road	1
2020/07/18	10:00am	Dam 5 Water tree		Ring Road	1
2020/07/18	10:30am	Dam 5 Water tree		Haul Road	1
2020/07/18	11:10am	Dam 5 Water tree		Ring Road	1
2020/07/18	12:00pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/18	12:55pm	Dam 5 Water tree		Haul Road	1
2020/07/18	1:35pm	Dam 5 Water tree		Ring Road	1
2020/07/18	2:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/18	3:50pm	Dam 5 Water tree		Haul Road	1
2020/07/18	4:25pm	Dam 5 Water tree		Ring Road	1
2020/07/18	4:55pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/18	5:25pm	Dam 5 Water tree		Ring Road	1
2020/07/18	5:55pm	Dam 5 Water tree		Haul Road	1
2020/07/18	6:25pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/18	9:55pm	Dam 5 Water tree		Haul Road	1
2020/07/18	10:35pm	Dam 5 Water tree		North Dam Haul Road	1
2020/07/18	11:10pm	Dam 5 Water tree		West Dam Haul Road	1
2020/07/18	11:45pm	Dam 5 Water tree		Ring Road	1
2020/07/18	12:15am	Dam 5 Water tree		North Dam Haul Road	1
2020/07/18	12:50am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/18	1:35am	Dam 5 Water tree		South Dam Haul Road	1
TOTAL LOADS					23

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/19	8:00am	Dam 5 Water tree		Ring Road	1
2020/07/19	8:20am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/19	9:05am	Dam 5 Water tree		Ring Road	1
2020/07/19	10:20am	Dam 5 Water tree		Haul Road	1
2020/07/19	2:25pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/19	3:25pm	Dam 5 Water tree	South Dam		1
2020/07/19	6:45pm	Dam 5 Water tree	North Dam		1
2020/07/19	9:45pm	Dam 5 Water tree	North Dam		1
2020/07/19	10:15pm	Dam 5 Water tree	South Dam		1
2020/07/19	10:50pm	Dam 5 Water tree		Ring Road	1
2020/07/19	11:20pm	Dam 5 Water tree		Haul Road 8	1
2020/07/19	11:50pm	Dam 5 Water tree		Laydown 3 to mech tent	1
TOTAL LOADS					12

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: 20 000	(circle one) Litres/US Gallons	Contractor: New Gold
------------------	---------------------------	-----------------------------------	-------------------------

[illegible]

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/20	7:55am	Dam 5 Water tree	South Dam		1
2020/07/20	8:15am	Dam 5 Water tree		Ring Road	1
2020/07/20	8:45am	Dam 5 Water tree		Haul Road	1
2020/07/20	9:15am	Dam 5 Water tree		Ring Road	1
2020/07/20	10:00am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/20	10:30am	Dam 5 Water tree		Haul Road	1
2020/07/20	11:10am	Dam 5 Water tree		Ring Road	1
2020/07/20	12:05pm	Dam 5 Water tree		Haul Road	1
2020/07/20	12:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/20	1:15pm	Dam 5 Water tree		Ring Road	1
2020/07/20	1:40pm	Dam 5 Water tree		Haul Road	1
2020/07/20	2:20pm	Dam 5 Water tree		Ring Road	1
2020/07/20	3:10pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/20	3:40pm	Dam 5 Water tree		Haul Road	1
2020/07/20	4:25pm	Dam 5 Water tree		Ring Road	1
2020/07/20	5:10pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/20	5:45pm	Dam 5 Water tree		Ring Road	1
2020/07/20	6:15pm	Dam 5 Water tree		Ring Road	1
2020/07/20	6:45pm	Dam 5 Water tree		Haul Road	1
2020/07/20	8:10pm	Dam 5 Water tree	North Dam Clay Core		1
2020/07/20	8:35pm	Dam 5 Water tree		Ring Road	1
2020/07/20	9:00am	Dam 5 Water tree		Haul Road 8	1
2020/07/20	9:30pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/20	10:50pm	Dam 5 Water tree	North Dam Clay Core		1
2020/07/20	11:20pm	Dam 5 Water tree		Ring Road	1
TOTAL LOADS					25

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/21	8:20am	Dam 5 Water tree	North Dam		1
2020/07/21	12:10pm	Dam 5 Water tree		Ring Road	1
2020/07/21	12:45pm	Dam 5 Water tree		Haul Road	1
2020/07/21	1:30pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/21	2:00pm	Dam 5 Water tree		Ring Road	1
2020/07/21	3:40pm	Dam 5 Water tree		Haul Road	1
2020/07/21	4:10pm	Dam 5 Water tree		Haul Road	1
2020/07/21	4:40pm	Dam 5 Water tree		Ring Road	1
2020/07/21	5:20pm	Dam 5 Water tree		Haul Road	1
2020/07/21	5:50pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/21	6:30pm	Dam 5 Water tree		Ring Road	1
2020/07/21	4:45am	Dam 5 Water tree	South Dam Clay Core		1
TOTAL LOADS					12

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/22	7:50am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/22	8:30am	Dam 5 Water tree		Ring Road	1
2020/07/22	9:05am	Dam 5 Water tree		Haul Road	1
2020/07/22	9:40am	Dam 5 Water tree		Ring Road	1
2020/07/22	10:10am	Dam 5 Water tree	South Dam Clay Core		1
2020/07/22	10:40am	Dam 5 Water tree		Haul Road	1
2020/07/22	11:25am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/22	11:55am	Dam 5 Water tree		Ring Road	1
2020/07/22	12:35pm	Dam 5 Water tree		Haul Road	1
2020/07/22	1:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/22	2:20pm	Dam 5 Water tree	North Dam Clay Core		1
2020/07/22	2:55pm	Dam 5 Water tree		Ring Road	1
2020/07/22	3:25pm	Dam 5 Water tree		Haul Road	1
2020/07/22	4:15pm	Dam 5 Water tree		Ring Road	1
2020/07/22	4:42pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/22	5:15pm	Dam 5 Water tree		Ring Road	1
2020/07/22	5:50pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/22	6:30pm	Dam 5 Water tree		Ring Road	1
2020/07/22	12:30am	Dam 5 Water tree	North Dam Clay Core		1
			TOTAL LOADS		19

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID:	Truck Capacity: (circle one) Litres/US Gallons	Contractor:
-----------	---	-------------

[illegible]

Submit completed forms to:

New Gold RRM Environment

Department

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/30	2:55pm	Dam 5 Water tree	South Dam		1
2020/07/30	3:25pm	Dam 5 Water tree	North Dam		1
2020/07/30	4:15pm	Dam 5 Water tree		Ring Road	1
2020/07/30	4:40pm	Dam 5 Water tree		Haul Road	1
2020/07/30	5:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/30	5:55pm	Dam 5 Water tree		Haul Road	1
2020/07/30	6:30pm	Dam 5 Water tree		Haul Road	1
			TOTAL LOADS		7

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/07/31	8:05am	Dam 5 Water tree	South Dam		1
2020/07/31	8:45am	Dam 5 Water tree		Ring Road	1
2020/07/31	9:25am	Dam 5 Water tree		Haul Road	1
2020/07/31	9:55am	Dam 5 Water tree	North Dam		1
2020/07/31	10:30am	Dam 5 Water tree		Haul Road	1
2020/07/31	11:05am	Dam 5 Water tree		Ring Road	1
2020/07/31	12:00pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/31	12:35pm	Dam 5 Water tree	North Dam		1
2020/07/31	1:05pm	Dam 5 Water tree		Haul Road	1
2020/07/31	1:35pm	Dam 5 Water tree		Haul Road	1
2020/07/31	2:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/31	2:45pm	Dam 5 Water tree		Haul Road	1
2020/07/31	4:00pm	Dam 5 Water tree		Haul Road	1
2020/07/31	4:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/07/31	5:40pm	Dam 5 Water tree		Haul Road	1
2020/07/31	6:20pm	Dam 5 Water tree		Laydown 3 to mech tent	1
			TOTAL LOADS		16

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Ralnyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/01	8:10am	Dam 5 Water tree		Haul Road	1
2020/08/01	8:40am	Dam 5 Water tree		Ring Road	1
2020/08/01	9:10am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/01	9:40am	Dam 5 Water tree		Haul Road	1
2020/08/01	10:15am	Dam 5 Water tree		Ring Road	1
2020/08/01	10:50am	Dam 5 Water tree		Haul Road	1
2020/08/01	11:30am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/01	11:55am	Dam 5 Water tree		Haul Road	1
2020/08/01	12:25pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/01	1:00pm	Dam 5 Water tree		Haul Road	1
TOTAL LOADS					10

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/02	8:05am	Dam 5 Water tree		Ring Road	1
2020/08/02	8:30am	Dam 5 Water tree		Haul Road	1
2020/08/02	9:05am	Dam 5 Water tree		Ring Road	1
2020/08/02	9:45am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/02	10:45am	Dam 5 Water tree		Haul Road	1
2020/08/02	11:40am	Dam 5 Water tree		Ring Road	1
2020/08/02	12:05pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/02	12:40pm	Dam 5 Water tree		Haul Road	1
2020/08/02	1:20pm	Dam 5 Water tree		Ring Road	1
2020/08/02	1:45pm	Dam 5 Water tree		Ring Road	1
2020/08/02	2:15pm	Dam 5 Water tree		Haul Road	1
2020/08/02	2:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/02	3:40pm	Dam 5 Water tree		Haul Road	1
2020/08/02	4:25pm	Dam 5 Water tree		Ring Road	1
2020/08/02	4:55pm	Dam 5 Water tree		Haul Road	1
2020/08/02	5:25pm	Dam 5 Water tree		Ring Road	1
2020/08/02	5:55pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/02	6:25pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		18

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/03	8:10am	Dam 5 Water tree	North Dam		1
2020/08/03	8:40am	Dam 5 Water tree		Ring Road	1
2020/08/03	9:15am	Dam 5 Water tree		Haul Road	1
2020/08/03	9:50am	Dam 5 Water tree		Ring Road	1
2020/08/03	10:35am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/03	11:00am	Dam 5 Water tree		Haul Road	1
2020/08/03	11:45am	Dam 5 Water tree		Ring Road	1
2020/08/03	12:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/03	12:50pm	Dam 5 Water tree		Haul Road	1
2020/08/03	1:15pm	Dam 5 Water tree		Ring Road	1
2020/08/03	1:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/03	2:20pm	Dam 5 Water tree		Ring Road	1
2020/08/03	2:50pm	Dam 5 Water tree		Haul Road	1
2020/08/03	3:20pm	Dam 5 Water tree		Ring Road	1
2020/08/03	3:45pm	Dam 5 Water tree		Ring Road	1
2020/08/03	4:25pm	Dam 5 Water tree		Haul Road	1
2020/08/03	5:00pm	Dam 5 Water tree		Ring Road	1
2020/08/03	6:25pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		18

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/04	8:00am	Dam 5 Water tree		Ring Road	1
2020/08/04	8:30am	Dam 5 Water tree		Haul Road	1
2020/08/04	9:10am	Dam 5 Water tree	North Dam		1
2020/08/04	9:35am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/04	10:10am	Dam 5 Water tree		Ring Road	1
2020/08/04	10:40am	Dam 5 Water tree		Haul Road	1
2020/08/04	11:45am	Dam 5 Water tree	North Dam		1
2020/08/04	12:15pm	Dam 5 Water tree		Ring Road	1
2020/08/04	12:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/04	1:15pm	Dam 5 Water tree		Haul Road	1
2020/08/04	1:50pm	Dam 5 Water tree		Ring Road	1
2020/08/04	2:40pm	Dam 5 Water tree	North Dam		1
2020/08/04	3:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/04	4:00pm	Dam 5 Water tree		Haul Road	1
2020/08/04	4:25pm	Dam 5 Water tree		Ring Road	1
2020/08/04	5:00pm	Dam 5 Water tree		Ring Road	1
2020/08/04	5:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/04	6:10pm	Dam 5 Water tree		Haul Road	1
2020/08/04	6:40pm	Dam 5 Water tree		Haul Road	1
			TOTAL LOADS		19

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/05	8:05am	Dam 5 Water tree	North Dam		1
2020/08/05	8:40am	Dam 5 Water tree		Ring Road	1
2020/08/05	9:20am	Dam 5 Water tree		Haul Road	1
2020/08/05	9:55am	Dam 5 Water tree		Ring Road	1
2020/08/05	10:30am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/05	11:20am	Dam 5 Water tree	North Dam		1
2020/08/05	12:25pm	Dam 5 Water tree		Haul Road	1
2020/08/05	1:00pm	Dam 5 Water tree		Ring Road	1
2020/08/05	1:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/05	2:20pm	Dam 5 Water tree	North Dam		1
2020/08/05	2:50pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/05	3:50pm	Dam 5 Water tree		Ring Road	1
2020/08/05	4:25pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/05	5:05pm	Dam 5 Water tree		Ring Road	1
2020/08/05	5:35pm	Dam 5 Water tree		Ring Road	1
2020/08/05	6:05pm	Dam 5 Water tree		Ring Road	1
2020/08/05	6:40pm	Dam 5 Water tree		Haul Road	1
2020/08/05	8:15pm	Dam 5 Water tree	North Dam		1
2020/08/05	10:45pm	Dam 5 Water tree	North Dam		1
2020/08/05	12:15am	Dam 5 Water tree	North Dam		1
2020/08/05	2:15am	Dam 5 Water tree	North Dam		1
			TOTAL LOADS		21

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/06	8:10am	Dam 5 Water tree	North Dam		1
2020/08/06	8:35am	Dam 5 Water tree		Ring Road	1
2020/08/06	9:05am	Dam 5 Water tree		Haul Road	1
2020/08/06	9:35am	Dam 5 Water tree		Ring Road	1
2020/08/06	10:20am	Dam 5 Water tree	North Dam		1
2020/08/06	11:00am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/06	11:45am	Dam 5 Water tree		Haul Road	1
2020/08/06	12:15pm	Dam 5 Water tree		Ring Road	1
2020/08/06	12:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/06	1:20pm	Dam 5 Water tree		Ring Road	1
2020/08/06	2:25pm	Dam 5 Water tree		Haul Road	1
2020/08/06	3:05pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/06	4:05pm	Dam 5 Water tree		Ring Road	1
2020/08/06	4:45pm	Dam 5 Water tree		Haul Road	1
2020/08/06	5:20pm	Dam 5 Water tree		Ring Road	1
2020/08/06	5:45pm	Dam 5 Water tree		Haul Road	1
2020/08/06	6:25pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/06	8:15pm	Dam 5 Water tree	North Dam		1
2020/08/06	9:00pm	Dam 5 Water tree		Ring Road	1
2020/08/06	9:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/06	10:30pm	Dam 5 Water tree		Ring Road	1
TOTAL LOADS					21

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/07	8:00am	Dam 5 Water tree	North Dam		1
2020/08/07	8:30am	Dam 5 Water tree		Ring Road	1
2020/08/07	9:10am	Dam 5 Water tree		Haul Road	1
2020/08/07	9:50am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/07	10:20am	Dam 5 Water tree		Ring Road	1
2020/08/07	10:50am	Dam 5 Water tree	North Dam		1
2020/08/07	11:55am	Dam 5 Water tree		Haul Road	1
2020/08/07	12:25pm	Dam 5 Water tree		Ring Road	1
2020/08/07	1:00pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/07	1:30pm	Dam 5 Water tree		Haul Road	1
2020/08/07	2:05pm	Dam 5 Water tree		Ring Road	1
2020/08/07	2:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/07	3:55pm	Dam 5 Water tree		Haul Road	1
2020/08/07	4:25pm	Dam 5 Water tree		Ring Road	1
2020/08/07	4:55pm	Dam 5 Water tree		Haul Road	1
2020/08/07	5:25pm	Dam 5 Water tree		Ring Road	1
2020/08/07	6:05pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/07	6:40pm	Dam 5 Water tree		Haul Road	1
2020/08/07	7:00pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		19

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/08	10:30am	Dam 5 Water tree	North Dam		1
2020/08/08	12:15pm	Dam 5 Water tree		Ring Road	1
2020/08/08	1:15pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/08	2:30pm	Dam 5 Water tree	North Dam		1
2020/08/08	3:45pm	Dam 5 Water tree		Ring Road	1
2020/08/08	4:45pm	Dam 5 Water tree		Haul Road	1
2020/08/08	5:40pm	Dam 5 Water tree		Ring Road	1
2020/08/08	6:20pm	Dam 5 Water tree		Ring Road	1
2020/08/08	10:30pm	Dam 5 Water tree		South Dam Haul Road	1
2020/08/08	11:00pm	Dam 5 Water tree		West Dam Haul Road	1
2020/08/08	11:30pm	Dam 5 Water tree		North Dam Haul Road	1
2020/08/08	1:30am	Dam 5 Water tree		North Dam Haul Road	1
TOTAL LOADS					12

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/09	7:50am	Dam 5 Water tree	North Dam		1
2020/08/09	8:20am	Dam 5 Water tree		Ring Road	1
2020/08/09	9:25am	Dam 5 Water tree		Haul Road	1
TOTAL LOADS					3

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/10	9:55am	Dam 5 Water tree	North Dam		1
2020/08/10	12:40pm	Dam 5 Water tree	West Dam		1
2020/08/10	4:00pm	Dam 5 Water tree		Ring Road	1
2020/08/10	4:30pm	Dam 5 Water tree		Haul Road	1
2020/08/10	5:00pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/10	6:15pm	Dam 5 Water tree		Haul Road	1
2020/08/10	6:40pm	Dam 5 Water tree	North Dam		1
2020/08/10	8:55pm	Dam 5 Water tree		Haul Road	1
2020/08/10	9:25pm	Dam 5 Water tree	West Dam		1
TOTAL LOADS					9

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/11	8:10am	Dam 5 Water tree	North Dam		1
2020/08/11	9:15am	Dam 5 Water tree		Ring Road	1
2020/08/11	10:05am	Dam 5 Water tree		Haul Road	1
2020/08/11	10:55am	Dam 5 Water tree		Ring Road	1
2020/08/11	11:50am	Dam 5 Water tree	West Dam		1
2020/08/11	12:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/11	1:25pm	Dam 5 Water tree		Ring Road	1
2020/08/11	2:05pm	Dam 5 Water tree		Haul Road	1
2020/08/11	3:00pm	Dam 5 Water tree	West Dam		1
2020/08/11	4:00pm	Dam 5 Water tree		Ring Road	1
2020/08/11	4:50pm	Dam 5 Water tree		Ring Road	1
2020/08/11	5:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/11	6:25pm	Dam 5 Water tree		Ring Road	1
2020/08/11	8:25pm	Dam 5 Water tree	West Dam		1
2020/08/11	9:30pm	Dam 5 Water tree	North Dam		1
			TOTAL LOADS		15

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/11	8:10am	Dam 5 Water tree	North Dam		1
2020/08/11	9:15am	Dam 5 Water tree		Ring Road	1
2020/08/11	10:05am	Dam 5 Water tree		Haul Road	1
2020/08/11	10:55am	Dam 5 Water tree		Ring Road	1
2020/08/11	11:50am	Dam 5 Water tree	West Dam		1
2020/08/11	12:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/11	1:25pm	Dam 5 Water tree		Ring Road	1
2020/08/11	2:05pm	Dam 5 Water tree		Haul Road	1
2020/08/11	3:00pm	Dam 5 Water tree	West Dam		1
2020/08/11	4:00pm	Dam 5 Water tree		Ring Road	1
2020/08/11	4:50pm	Dam 5 Water tree		Ring Road	1
2020/08/11	5:35pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/11	6:25pm	Dam 5 Water tree		Ring Road	1
2020/08/11	8:25pm	Dam 5 Water tree	West Dam		1
2020/08/11	9:30pm	Dam 5 Water tree	North Dam		1
TOTAL LOADS					15

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/12	8:15am	Dam 5 Water tree	North Dam		1
2020/08/12	8:55am	Dam 5 Water tree		Ring Road	1
2020/08/12	9:40am	Dam 5 Water tree		Haul Road	1
2020/08/12	10:15am	Dam 5 Water tree	West Dam		1
2020/08/12	10:55am	Dam 5 Water tree		Ring Road	1
2020/08/12	11:20am	Dam 5 Water tree	West Dam		1
2020/08/12	11:55am	Dam 5 Water tree		Ring Road	1
2020/08/12	12:20pm	Dam 5 Water tree		Haul Road	1
2020/08/12	12:55pm	Dam 5 Water tree	West Dam		1
2020/08/12	1:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/12	2:15pm	Dam 5 Water tree		Ring Road	1
2020/08/12	2:50pm	Dam 5 Water tree		Haul Road	1
2020/08/12	3:45pm	Dam 5 Water tree	West Dam		1
2020/08/12	4:20pm	Dam 5 Water tree		Ring Road	1
2020/08/12	4:55pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/12	5:30pm	Dam 5 Water tree		Ring Road	1
2020/08/12	6:05pm	Dam 5 Water tree	West Dam		1
2020/08/12	6:35pm	Dam 5 Water tree		Ring Road	1
2020/08/12	12:25am	Dam 5 Water tree	West Dam	Haul Road	1
2020/08/12	1:00am	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/12	1:30am	Dam 5 Water tree	North Dam	Haul Road	1
			TOTAL LOADS		21

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:

New Gold RRM Environment Dept.

Rainyriver.enviro@newgold.com

On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/12	8:05am	Dam 5 Water tree	West Dam 4		1
2020/08/12	8:50am	Dam 5 Water tree		Ring Road	1
2020/08/12	9:35am	Dam 5 Water tree		Haul Road	1
2020/08/12	11:00am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/12	11:55am	Dam 5 Water tree	West Dam 5		1
2020/08/12	12:40pm	Dam 5 Water tree		Ring Road	1
2020/08/12	1:25pm	Dam 5 Water tree		Haul Road	1
2020/08/12	2:20pm	Dam 5 Water tree		Ring Road	1
2020/08/12	3:05pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/12	3:55pm	Dam 5 Water tree		Haul Road	1
2020/08/12	4:50pm	Dam 5 Water tree		Ring Road	1
2020/08/12	5:40pm	Dam 5 Water tree		Ring Road	1
2020/08/12	6:25pm	Dam 5 Water tree		Haul Road	1
TOTAL LOADS					13

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

Haulage Daily Report

Name: 15/08/2020
 Date: 234
 Truck ID: 10171
 Engine Hours: 10171

Crew:
 Shift:

Circle one from each option
 A B C D
 Day Night

newgold

Load	Loading Unit	From	To	Tonnes	Material
1	MFS		Pit - PAG Road		1
2	"		"	"	1
3					
4					
5	MFS		Pag Road		1
6	"	Copper S	"	"	1
7	"	Copper N	"	"	1
8	"	Copper	"	"	1
9	"	"	"	"	1
10	"	Copper S	"	"	1
11	"	Pit	"	"	1
12	"	Copper N/S	"	"	1
13	"	"	"	"	1
14	"	SHR Pit			1
15					
16					
17					
18					
19					
20					

16/08/2020

Load	Loading Unit	From	To	Tonnes	Material
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					

Supervisor Signature: _____

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record

Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/15	4:45pm	Dam 5 Water tree	4:45pm	Ring Road	1
2020/08/15	5:25pm	Dam 5 Water tree	5:25pm	Laydown 3 to mech tent	1
2020/08/15	5:55pm	Dam 5 Water tree	5:55pm	Ring Road	1
			TOTAL LOADS		3

Water Truck Maintenance and Repair Record

Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/16	9:00am	Dam 5 Water tree	West Dam	Haul Road	1
2020/08/16	9:45am	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/16	10:15am	Dam 5 Water tree	Dam 5		1
2020/08/16	11:05am	Dam 5 Water tree	West Dam	Haul Road	1
2020/08/16	12:00pm	Dam 5 Water tree	North Dam	Haul Road	1
2020/08/16	12:40pm	Dam 5 Water tree	West Dam	Haul Road	1
			TOTAL LOADS		6

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/16	8:05am	Dam 5 Water tree	West Dam		1
2020/08/16	8:30am	Dam 5 Water tree		Ring Road	1
2020/08/16	9:05am	Dam 5 Water tree	North Dam		1
2020/08/16	9:45am	Dam 5 Water tree		Haul Road	1
2020/08/16	10:15am	Dam 5 Water tree		Ring Road	1
2020/08/16	10:55am	Dam 5 Water tree	West Dam		1
2020/08/16	11:50am	Dam 5 Water tree		Ring Road	1
2020/08/16	12:40pm	Dam 5 Water tree		Haul Road	1
2020/08/16	1:15pm	Dam 5 Water tree	North Dam		1
2020/08/16	1:50pm	Dam 5 Water tree		Ring Road	1
2020/08/16	2:20pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/16	2:55pm	Dam 5 Water tree	West Dam		1
2020/08/16	3:55pm	Dam 5 Water tree		Haul Road	1
2020/08/16	4:50pm	Dam 5 Water tree		Ring Road	1
2020/08/16	5:40pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/16	6:25pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		16

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Haulage Daily Report

Name: M. McIntyre
Date: August 17, 2020
Truck ID: 234
Engine Hours: 10195.0

Crew: _____
Shift: _____

Circle one from each option
A B C D
Day Night

newgold

Load	Loading Unit	From	To	Tonnes	Material
820 1	Pit water	Pit	Chopper	11A	water
926 2	Pit water	Pit	Chopper	11A	water
1030 3	Pit water	Pit	Chopper	11A	water
1145 4	Pit water	Pit	Chopper	11A	water
1258 5	Pit water	Pit	Chopper	11A	water
1445 6	Pit water	Pit	Chopper	11A	water
7					
4: 8	Ex w.t.	Pit			
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					

Load	Loading Unit	From	To	Tonnes	Material
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					

Supervisor Signature: _____

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-252	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/17	8:15am	Dam 5 Water tree	Dam 5		1
2020/08/17	9:00am	Dam 5 Water tree		Haul Road	1
2020/08/17	9:35am	Dam 5 Water tree		Haul Road	1
2020/08/17	10:35am	Dam 5 Water tree	North Dam		1
2020/08/17	11:15am	Dam 5 Water tree		Haul Road	1
2020/08/17	11:50am	Dam 5 Water tree		Haul Road	1
2020/08/17	12:25pm	Dam 5 Water tree		Haul Road	1
2020/08/17	1:05pm	Dam 5 Water tree		Haul Road	1
2020/08/17	1:30pm	Dam 5 Water tree		Haul Road	1
2020/08/17	2:05pm	Dam 5 Water tree		Haul Road	1
2020/08/17	2:55pm	Dam 5 Water tree		Haul Road	1
TOTAL LOADS					11

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/17	8:05am	Dam 5 Water tree		Ring Road	1
2020/08/17	8:45am	Dam 5 Water tree		Haul Road	1
2020/08/17	9:20am	Dam 5 Water tree		Laydown 3 to meech tent	1
2020/08/17	9:45am	Dam 5 Water tree	West Dam		1
2020/08/17	10:20am	Dam 5 Water tree		Ring Road	1
2020/08/17	11:10am	Dam 5 Water tree		Haul Road	1
2020/08/17	11:45am	Dam 5 Water tree	North Dam		1
2020/08/17	12:20pm	Dam 5 Water tree		Haul Road	1
2020/08/17	1:00pm	Dam 5 Water tree		Ring Road	1
2020/08/17	2:30pm	Dam 5 Water tree		Laydown 3 to meech tent	1
2020/08/17	3:15pm	Dam 5 Water tree	North Dam		1
2020/08/17	4:10pm	Dam 5 Water tree		Ring Road	1
2020/08/17	5:00pm	Dam 5 Water tree	West Dam		1
2020/08/17	5:45pm	Dam 5 Water tree		Haul Road	1
2020/08/17	6:25pm	Dam 5 Water tree		Ring Road	1
2020/08/17	6:45pm	Dam 5 Water tree		Ring Road	1
			TOTAL LOADS		16

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Haulage Daily Report

10218 829

newgold

Name: 18/08/2020
 Date: 234
 Truck ID: 102 14
 Engine Hours: 102 14

Circle one from each option

Crew: A
 Shift: Day

A B C D
 Day Night

Reels

time

Load	Truck Loading Unit	From	To	Reels	# of Loads Material
1	MFJ	7:50	Copper Hills	1	1
2	"	9:00	"	"	1
3	"	1:10	"	"	1
4	"	2:10	"	SHR-8	1
5	"	3:20	PT / SHR / HRB	"	1
6	"	4:30	"	PAC	1
7	"	5:35	"	"	1
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					

Load	Loading Unit	From	To	Tonnes	Material
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					

Supervisor Signature: _____

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
------------------------	--------------------------------------	---

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/18	8:30am	Dam 5 Water tree	North Dam		1
2020/08/18	9:45am	Dam 5 Water tree		Haul Road	1
2020/08/18	10:35am	Dam 5 Water tree	West Dam		1
2020/08/18	12:20pm	Dam 5 Water tree		Ring Road	1
2020/08/18	1:25pm	Dam 5 Water tree	North Dam		1
2020/08/18	2:30pm	Dam 5 Water tree		Haul Road	1
2020/08/18	2:55pm	Dam 5 Water tree		Ring Road	1
2020/08/18	3:50pm	Dam 5 Water tree			1
2020/08/18	4:20pm	Dam 5 Water tree	West Dam		1
2020/08/18	5:10pm	Dam 5 Water tree		Ring Road	1
2020/08/18	6:10pm	Dam 5 Water tree		Ring Road	1
2020/08/18	6:45pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/18	1:10am	Dam 5 Water tree		Haul Road	1
2020/08/18	1:40am	Dam 5 Water tree		Haul Road	1
2020/08/18	2:25am	Dam 5 Water tree		Laydown 3 to mech tent	1
TOTAL LOADS					15

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
 New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
 On-call Phone: 807-632-6152

2020 Water Application and Truck Maintenance Form – Contractors

Truck ID: 4-251	Truck Capacity: 20,000 Litres	Contractor: Sigfusson Northern LTD
-----------------	-------------------------------	------------------------------------

Water Application Record					
Date (YY/MM/DD)	Time (00:00 hrs)	Water Source Location	Watering Locations Area	Watering Locations Roadway	Number of Full Loads
2020/08/19	8:05am	Dam 5 Water tree		Ring Road	1
2020/08/19	8:55am	Dam 5 Water tree		Haul Road	1
2020/08/19	9:35am	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/19	4:10pm	Dam 5 Water tree		Ring Road	1
2020/08/19	4:55pm	Dam 5 Water tree		Haul Road	1
2020/08/19	5:35pm	Dam 5 Water tree		Haul Road	1
2020/08/19	6:00pm	Dam 5 Water tree		Laydown 3 to mech tent	1
2020/08/19	6:35pm	Dam 5 Water tree	North Dam		1
			TOTAL LOADS		8

Water Truck Maintenance and Repair Record	
Date	Description of Repair, Servicing or Routine Maintenance

Submit completed forms to:
New Gold RRM Environment Dept.
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152

Truck ID: 234	Truck Capacity: (circle one) Litres/US Gallons	New Gold Area/Dept: mine ops
---------------	---	---------------------------------

[illegible]

Submit completed forms to:
New Gold RRM Environment
Department
Rainyriver.enviro@newgold.com
On-call Phone: 807-632-6152